

Our Job Ref No : 305485754
Date : 10/09/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Lanyang Drive Singapore 608969
Fax: 6546 6156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SH 7769C

Date of Accident : 04/09/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG ASIA --- GBE8523E

2. The finalized amount shall be:

(a) Spare Parts after List discount \$1,259.60

(b) Labour Charges \$1,230.00

Total for Part-By-Part Repair Cost \$2,489.60

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : LIM T S

Name : THEVAN

Tel : 62148398

Date : 14/9/21

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 6-Sep-21

MODEL: Hyundai Ioniq

INSURANCE: AIG ASIA

VEHICLE NO.: SH 7769C

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Boot Lid Assy	1		2480.40 R
	Boot Lid Emblem-Hybrid	1		\$24.30 ✓ NCC
	Boot Lid Emblem-Ioniq	1		\$31.30 ✓ NCC
	Boot Lid Lower Glass (Black)	1		\$584.90 X SUC
	Rear Bumper	1		\$459.40 ✓ Cut
	Rear Bumper Reinforcement	1		\$394.80 X SUC
	Rear Bumper Reinforcement Bracket RH/LH	2	\$138.10	\$276.20 X SUC
	Rear Bumper Centre Moulding Assy	1		\$451.25 ✓ Cut
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 ✓ Cut
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 ✓ NCC
	Rear Bumper Reflector Lamp RH	1		\$41.45 X SUC
	Boot Lid Lamp RH	1		\$794.40 X SUC
	Rear Bumper Fog Lamp	1		\$201.50 X SUC
	SUB TOTAL			\$5,916.90
	LESS 20%			\$1,183.38
	DISCOUNTED TOTAL			\$4,733.52
	Boot Lid ComfortDelGro	1		\$35.00 ✓ NCC
	Boot Lid 65521111	1		\$35.00 ✓ NCC
	Boot Lid APPS	1		\$40.00 ✓ NCC
	Rear Bumper Reverse Sensor	1		\$180.00 ✓ Cut
	Rear No. Plate W/Trim Cover	1		\$55.00 ✓ CRA
	Rear Windscreen Sealant	2	\$46.00	\$92.00 X N/A
	S/NETT TOTAL			\$437.00
	SPARE PARTS TOTAL			\$5,170.52
	Labour Charge			
	Panel Beating			\$800.00 700
	Spray Painting Charge			\$600.00 500
	Remove/Refix Reverse Sensor			\$120.00 30
	Remove/Refix Both Rear Glasses			\$240.00 X N/A
	TOTAL LABOUR			\$1,760.00
	ESTIMATE TOTAL			\$6,930.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tharon Cth A
tharon@lkhauto.com
62238769
6/9/21 1630
3 delays w/p
b repaint photos