



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9488C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT RH FENDER	BADLY DENTED	780.00	732.00
1	FRONT RH FENDER COWLING	DISTORTED	466.00	318.00
1	SET FRONT RH FENDER COWLING CLIPS	NECESSARY	60.00	50.00
1	FRONT RH FENDER CORNER COVER	NOT NECESSARY	226.00	-
1	FRONT RH BUMPER	DISTORTED	1,245.50	855.30
1	SET FRONT RH BUMPER CLIPS	NECESSARY	68.00	50.00
1	FRONT RH BUMPER BRACKET O/S	CRACKED	171.80	101.00
1	FRONT RH HEADLAMP ASSEMBLY	CRACKED	658.70	658.70
1	FRONT RH HEAD LAMP LOWER PANEL	TO REPAIR SEE LABOUR	370.00	-
1	FRONT RH TYRE	SERVICEABLE	195.00	-
1	FRONT RH LOWER ARM	NOT NECESSARY	648.00	-
1	FRONT RH KNUCKLE ARM	BENT	620.20	620.20
1	FRONT RH KNUCKLE ARM BEARING	NECESSARY	322.50	265.00
1	FRONT RH SUSPENSION	BENT	380.00	380.00
	LESS 10% DISCOUNT		-	-403.02
			6,211.70	3,627.18
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT RH WHEEL STEEL RIM (SN)	BENT	679.00	50.00
			679.00	50.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		50.00	20.00
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE PARTS & COMPONENTS.		400.00	120.00
	TO CHECK & RE-ADJUST WHEEL ALIGNMENT.		50.00	50.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF FRONT RH HEAD LAMP LOWER PANEL.		800.00	500.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		600.00	600.00

Report Ref No. CS/SMR21009334/Uuf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		60.00	40.00
			1,960.00	1,330.00
GRAND TOTAL			8,850.70	5,007.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/SMR21009334/Uuf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.