

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21009344/VES3Q2
Date: 09/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900246338
Claimant Vehicle No :	SH8553B	Insured Vehicle No :	SKC85J
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	9063022131SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8553B	Engine No:	G4LEKU403505
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU188567
Reg. Date:	30/10/2019 (Man. Year: 2019)	Odometer:	233623 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,663.88	1,989.44	2,674.44	57.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,290.00	240.00	15.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,193.88	3,279.44	2,914.44	47.05
+ GST 7.00/7.00% (S\$)	433.57	229.56	204.01	47.05

Nett Amount (S\$)	6,627.45	3,509.00	3,118.45	47.05
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,386.95		
Global Sum Settlement (S\$)		4,380.00		

INSPECTION

Date of Assignment: 06/09/2021

Date Inspected: 06/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: Thevan Thomas Karthikesavan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Dented	394.80 FL	*394.80 FL
4	2		*REAR BUMPER STAY LH/RH	Serviceable	276.20 FL	*- FL
5	1		*REAR BUMPER LOWER CENTRE MOULDING	Cut	155.00 FL	*155.00 FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
7	1		*BOOTLID COVER	Repair	2,480.40 FL	*- FL
8	1		*BOOTLID LOCK UPPER	Serviceable	224.00 FL	*- FL
9	1		*BOOTLID H EMBLEM	Necessary	38.00 FL	*38.00 FL
10	1		*BOOTLID EMBLEM IONID	Necessary	31.80 FL	*31.80 FL
11	1		*BOOTLID EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
12	1		*BUMPER FOG LAMP	Cut	201.00 FL	*201.00 FL
13	2		*BUMPER NUMBER LAMP LH/RH	Serviceable	170.60 FL	*- FL
14	1		*BUMPER HOOK COVER	Serviceable	94.60 FL	*- FL
15	1		*REAR REFLECTOR LH	Serviceable	41.45 FL	*- FL
16	1		*REAR ANTENNA -SMART KEY	Cut	40.50 FL	*40.50 FL
17	2		*REAR BUMPER BRACKET LH/RH	Serviceable	55.80 FL	*- FL
18	1		*BOOTLID ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
19	1		*REAR BUMPER ADVERTISEMENT	Necessary	100.00 FS	*100.00 FS
20	1		*BOOTLID COMFORT APP STICKER	Necessary	40.00 FS	*40.00 FS
21	2		*BOOTLID COMFORT/TEL NUMBER STICKER	Necessary	60.00 FS	*60.00 FS
22	1		*REAR NUMBER PLATE W/HOLDER	Scratched	55.00 FS	*55.00 FS
23	1		*REAR REVERSE SENSOR	Cut	180.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,696.10	2,353.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,032.22	363.61
Total Parts (\$\$)	4,663.88	1,989.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	CHECK WIRING AND LIGHTING	New	60.00	30.00
4	TUFF KOTE	New	60.00	30.00
5	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (S\$)			1,530.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >