

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21009345/GTF3E2

Date: 19/01/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001443563		
Claimant Vehicle No :	SLN7203U	Insured Vehicle No :	SKP3565C		
Date of Loss:	04/09/2021	Nature of Claim:	TP	Claim No:	262132

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7203U	Engine No:	LEB5934895
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31234880
Reg. Date:	16/05/2017 (Man. Year: 2016)	Odometer:	40901 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Royal 6 mm	Rear Left Side:	Royal 6 mm
Front Right Side:	Royal 6 mm	Rear Right Side:	Royal 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,740.59	5,629.44	15,111.15	72.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,650.00	2,830.00	5,820.00	67.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>29,390.59</b>	<b>8,459.44</b>	<b>20,931.15</b>	<b>71.22</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,100.00</b>		
<b>(\$\$)</b>	29,390.59	6,100.00	23,290.59	79.25
<b>+ GST 7.00/7.00% (\$\$)</b>	2,057.34	427.00	1,630.34	79.25
<b>Nett Amount (\$\$)</b>	<b>31,447.93</b>	<b>6,527.00</b>	<b>24,920.93</b>	<b>79.25</b>

### INSPECTION

Date of Assignment:	06/09/2021	Kaizen Motors Pte Ltd (HQ) 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT Singapore 417896
Date Inspected:	07/09/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2021)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLN7203U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,278.48 F	*751.00 FL
2	2		*REAR BUMPER BRACKET	Broken	104.80 F	*55.80 FL
3	1		*REAR BUMPER REFLECTOR	N/S Cut / O/S Not Necessary	432.70 F	*141.00 FL
4	1		*REAR BUMPER SIDE GARNISH	N/S Deformed/O/S Not Necessary	517.52 F	*165.90 FL
5	1		*REAR REINFORCEMENT BEAM	Not Necessary	537.63 F	*- FL
6	1		*REAR TAILGATE	Buckled	1,386.38 F	*953.00 FL
7	1		*REAR TAILGATE RUBBER MOULDING	Necessary	197.80 FS	*40.00 FS
8	2		*REAR TAILGATE DAMPER	Not Necessary	360.90 F	*- FL
9	1		*REAR TAIL GATE INNER TRIMMING (2PCS)	Deformed (1Pc Only)	1,147.60 F	*205.50 FL
10	1		*REAR TAILGATE LOWER LINING ASSY	Not Necessary	372.16 F	*- FL
11	1		*REAR END PANEL	Bent	796.85 F	*517.00 FL
12	1		*REAR END PANEL TRIMMING	Deformed	203.44 F	*101.60 FL
13	1		*REAR SPARE TIRE WHEEL COMPARTMENT	Crumpled	1,223.25 F	*917.60 FL
14	2		*REAR TAIL LAMP INNER	Cracked	1,665.42 F	*650.00 FL
15	2		*REAR TAIL LAMP OUTER	Cracked	1,568.46 F	*920.40 FL
16	2		*REAR FENDER	Repair	2,758.72 F	*- FL
17	1		*REAR FENDER INNER TRIMMING	Deformed	669.08 F	*240.00 FL
18	1		*REAR FENDER WHEEL GUARD GARNISH	Deformed	355.10 F	*111.90 FL
19	1		*REAR HONDA EMBLEM	Necessary	70.44 F	*31.90 FL
20	1		*REAR VEZEL EMBLEM	Necessary	70.44 F	*56.20 FL
21	1		*REAR HYBRID EMBLEM	Necessary	101.80 F	*64.10 FL
22	1		*REAR TAIL GATE LOCKING MECHANISM	Jammed	192.18 F	*151.90 FL
23	1		*REAR TAIL GATE LOCKING PIN STRIKER	Jammed	70.40 F	*27.50 FL
24	1		*REAR TAIL GATE LOCKING SWITCH	Not Necessary	262.14 F	*- FL
25	1		*REAR WIPER MOTOR	Not Necessary	418.34 F	*- FL
26	1		*REAR LICENCE PLATE LAMP COVER	Not Necessary	233.60 F	*- FL
27	2		*REAR LICENCE PLATE LAMP	Not Necessary	158.04 F	*- FL
28	1		*SPARE TIRE TOOL BOX SPONGE ASSY	Deformed	339.40 F	*226.50 FL
29	1		*REAR LICENSE PLATE COVER	Scratched	50.00 FS	*20.00 FS
30	1		*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
31	20		*REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
32	10		*REAR TAIL LAMP CLIPS	Necessary	60.00 FS	*20.00 FS
33	10		*REAR TAILGATE TRIMMING CLIPS	Necessary	70.00 FS	*30.00 FS
34	10		*REAR TAILGATE SPOILER CLIPS	Not Necessary	70.00 FS	*- FS
35	4		*REAR REVERSE SENSOR	Damaged	500.00 FS	*200.00 FS
36	1		*SMART BUZZER ANTENNA ASSY	Damaged	231.32 F	*105.00 FL
37	2		*REAR INNER FENDER TRIM	Repeated	877.56 F	*- FL
38	1		*TYRE COMPARTMENT COVER (WOOD)	Bent	627.87 F	*205.50 FL
39	1		*TYRE COMPARTMENT COVER (PLASTIC)	Not Necessary	610.77 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>20,740.59</b>	<b>6,949.30</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$)</b>	0.00	1,319.86
<b>Total Parts (\$)</b>	<b>20,740.59</b>	<b>5,629.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR CHECKING ON WIRING	New	250.00	30.00
2	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS. INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF REAR END ASSY & PARTS	New	2,800.00	1,000.00
3	SPRAYPAINTING & PUTTY OF REAR BUMPER, REAR BOOT REAR DIFFUSER, END PANEL, BUMPER GARNISH	New	1,800.00	1,200.00
4	LABOUR FOR RETROFITTING MOULDING & SEAL	New	550.00	120.00
5	ALIGNMENT	New	150.00	0.00
6	LABOUR FOR DIAGNOSING & RESETTING OF FAULT ON TAIL LAMP & PARKING SENSOR	New	850.00	40.00
7	TRANSFERRING OF TAILGATE PARTS TO NEW TAILGATE	New	550.00	60.00
8	APPLYING OF RUST PROOFING	New	300.00	80.00
9	LABOUR FOR REMOVING HYBRID SYSTEM ON REAR WHEEL WELL FOR REPLACEMENT OF SPARE TIRE WHEEL WELL	New	850.00	150.00
10	LABOUR FOR DIAGNOSING & RESETTING OF FAULT ON HYBRID SYSTEM	New	550.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,650.00</b>	<b>2,830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >