

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009352/R1TCN2**Date:** 22/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00011042004

Claimant Vehicle No : SLM6483P **Insured Vehicle No :** CB9888A

Date of Loss: 01/09/2021 Nature of Claim: TP Claim No: SNM21D204942/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM6483P**

Make & Model: HONDA GRACE HYBRID, 1.5 DX (A) Engine No: LEB5255149

Reg. Date: 03/04/2017 (Man. Year: 2016) Chassis No: GM41105136

Colour: Grey Odometer: 252926 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Rydanz 6 mm Rear Left Side: Rydanz 6 mm

Front Right Side: Rydanz 6 mm Rear Right Side: Rydanz 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,040.00	980.00	60.00	5.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	650.00	250.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,940.00	1,630.00	310.00	15.98
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	1,940.00	1,300.00	640.00	32.99
+ GST 7.00/7.00% (S\$)	135.80	91.00	44.80	32.99
Nett Amount (S\$)	2,075.80	1,391.00	684.80	32.99

INSPECTION

Date of Assignment: 22/09/2021

Date Inspected: 07/09/2021 Inspected At: Lion City Rental (jalan Lam Huat) (HQ)
60 Jalan Lam Huat, 04-35/36 Carros Centre
Singapore 737869

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Sep 2021)
Parts: 143	HONDA GRACE HYBRID 1.5 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM6483P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Cracked	850.00 FL	*850.00 FL	
2	1		*FRONT GRILLE BASE	Cracked	450.00 FL	*375.00 FL	
					Sub Total (\$\$)	1,300.00	1,225.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	260.00	245.00
					Total Parts (\$\$)	1,040.00	980.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND F/L FENDER OUT FACILIAE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	500.00	250.00
2	TO RESPRAY FRONT BUMPER,F/L FENDER	New	400.00	400.00
			Gross Labour Cost (\$\$)	900.00
				650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >