

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009353/VUCN2
Date: 07/12/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00123062100
Claimant Vehicle No : SMF3645J **Insured Vehicle No :** SKB5169Z
Date of Loss: 03/09/2021 Nature of Claim: TP Claim No: SNM21D204984/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMF3645J**
Make & Model: NISSAN SYLPHY, 1.6 CVT (A) Engine No: HR16931396C
Reg. Date: 07/11/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0032951
Colour: Silver Odometer: 31562 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Bluearth 7 mm Rear Left Side: Bluearth 7 mm
Front Right Side: Bluearth 7 mm Rear Right Side: Bluearth 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	320.00	320.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,688.00	1,218.00	470.00	27.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,008.00	1,538.00	470.00	23.41
+ GST 7.00/7.00% (\$\$)	140.56	107.66	32.90	23.41
Nett Amount (\$\$)	2,148.56	1,645.66	502.90	23.41

INSPECTION

Date of Assignment: 06/09/2021
Date Inspected: 07/09/2021 Inspected At: Autolution Industrial Pte Ltd (Ubi)
19 Ubi Road 4
Singapore 408623
Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2021)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SMF3645J/07/12/2021 12:03	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH ALLOY RIM	Scratched	320.00 FS	*320.00 FS
						F=Franchise part. S=SpcNett.
Total Parts (S\$)					320.00	320.00

LKK Auto Consultants Pte Ltd/SMF3645J/07/12/2021 12:03. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR FRT RH FENDER AND FRT BUMPER.REMOVE AND INSTALL FRT BUMPER	New	780.00	560.00
2	CHARGES TO SPRAY PAINTING FRT RH FENDER AND FRT BUMPER	New	750.00	500.00
3	REMOVE AND INSTALL BOTH HEADLAMP AND FOCUS	New	48.00	48.00
4	RENEW FRT RH WHEEL RIM AND BALANCING	New	15.00	15.00
5	PERFORM WHEEL ALIGNMENT	New	95.00	95.00
Gross Labour Cost (\$\$)			1,688.00	1,218.00

LKK Auto Consultants Pte Ltd/SMF3645J/07/12/2021 12:03. Not valid without Reference section.

< END OF ESTIMATES >