



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 2901U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,635.00	1,635.00
2	REAR BUMPER SIDE HOLDER @\$79.00	NOT NECESSARY	158.00	-
1	REAR BUMPER LOWER GARNISH	DEFORMED	406.00	406.00
1	REAR BUMPER LOWER GARNISH CHROME MOULDING	CUT	286.00	286.00
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	655.00	-
1	REAR BUMPER CENTRE GUIDE	CRACKED	159.00	159.00
4	REVERSE SENSOR @\$265.00	DAMAGED (1 PC ONLY)	1,060.00	265.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,290.00	-
	LESS 10% DISCOUNT		-	-275.10
			5,649.00	2,475.90
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
			50.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	200.00
	SPRAY PAINTING.		800.00	200.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
			1,750.00	480.00
	GRAND TOTAL		7,449.00	2,985.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00

Report Ref No. CS/AGI21009354/Auf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.