

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/MSG21009356/DTF3E2**Date:** 26/10/2021**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001490499
<b>Claimant Vehicle No :</b>	SMU8882D	<b>Insured Vehicle No :</b>	SKP8618B
Date of Loss:	01/09/2021	Nature of Claim:	TP
		Claim No:	262171

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SMU8882D	Engine No:	S530435641
Make & Model:	MAZDA AXELA, 1.5 (A)	Chassis No:	BMLFP101399
Reg. Date:	07/06/2019 (Man. Year: 2019)	Odometer:	96279 km
Colour:	Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	Maxxis 5 mm	Rear Right Side:	Maxxis 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,940.00	1,380.88	5,559.12	80.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	750.00	4,570.00	85.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>12,260.00</b>	<b>2,130.88</b>	<b>10,129.12</b>	<b>82.62</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,700.00</b>		
<b>(\$\$)</b>	12,260.00	1,700.00	10,560.00	86.13
<b>+ GST 7.00/7.00% (\$\$)</b>	858.20	119.00	739.20	86.13
<b>Nett Amount (\$\$)</b>	<b>13,118.20</b>	<b>1,819.00</b>	<b>11,299.20</b>	<b>86.13</b>

**INSPECTION**

Date of Assignment:	06/09/2021	JWG International Pte Ltd (HQ)
Date Inspected:	07/09/2021 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	2.0 days	

**Adjuster:** BRYAN TANI**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
<b>Parts:</b>	144	MAZDA AXELA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMU8882D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT HAND SIDE MIRROR ASSY	Malfunctioned	2,800.00 FL	*1,726.10 FL
2	1		*FRONT RIGHT HAND FENDER	Not Necessary	890.00 FL	*- FL
3	1		*FRONT RIGHT HAND HEADLAMP	Repair	3,690.00 FL	*- FL
4	1		*FRONT BUMPER	Repair	1,080.00 FL	*- FL
5	1		*FRONT BUMPER RIGHT HAND SIDE RETAINER	Not Necessary	90.00 FL	*- FL
6	1		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
7	1		*FRONT BUMPER CLIPS	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,650.00</b>	<b>1,726.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,710.00	345.22
<b>Total Parts (\$\$)</b>	<b>6,940.00</b>	<b>1,380.88</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	600.00	0.00
2	TO REMOVE & PANEL BEAT ALL ABOVE DAMAGED PARTS & PANELS	New	2,000.00	300.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	300.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	0.00
5	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	0.00
6	TO COMPUTERISE / DIAGNOISE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,320.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >