

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009358/EEA3Q2**Date:** 19/04/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLA9881S	Insured Vehicle No :	SLM4990E
Date of Loss:	01/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA9881S	Engine No:	1ZRY222447
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104540839
Reg. Date:	23/03/2016 (Man. Year: 2015)	Odometer:	55118 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,914.31	718.43	1,195.88	62.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,635.00	460.00	1,175.00	71.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,549.31	1,178.43	2,370.88	66.80
Approved Total (Overridden) (\$\$)		950.00		
(\$\$)	3,549.31	950.00	2,599.31	73.23
+ GST 7.00/7.00% (\$\$)	248.45	66.50	181.95	73.23
Nett Amount (\$\$)	3,797.76	1,016.50	2,781.26	73.23
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment:	06/09/2021		
Date Inspected:	08/09/2021	Inspected At:	Ethoz Group Ltd (HQ) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA9881S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID (NPA)	Not Necessary	0.00 FL	*- FL
2	1		*REAR BOOTLID EMBLEM CENTRE	Not Necessary	75.52 FL	*- FL
3	1		*REAR BOOTLID EMBLEM COROLLA	Not Necessary	65.44 FL	*- FL
4	1		*REAR BOOTLID EMBLEM ALTIS	Not Necessary	65.44 FL	*- FL
5	1		*REAR BUMPER	Dented	654.25 FL	*492.00 FL
6	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH	Broken	84.62 FL	*84.62 FL
8	1		*REAR BUMPER SIDE RETAINER RH	Broken	84.62 FL	*84.62 FL
9	1		*REAR BUMPER REINFORCEMENT	Not Necessary	384.55 FL	*- FL
10	1		*REAR END PANEL	Not Necessary	553.64 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	214.34 FL	*- FL
12	1		*SPARE TYRE PANEL (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
14	1		*END PANEL SEALANT	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,472.42	891.24
- List Item Discount on L Items 25.00/25.00% (\$\$)	558.11	172.81
Total Parts (\$\$)	1,914.31	718.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CARRY OUT REAR REPAIR	New	800.00	200.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	30.00
3	TO SPRAY PAINTING ON REAR AFFECTED AREA	New	700.00	200.00
4	SPRAY RUST PROOF ON AFFECTED AREA	New	40.00	0.00
5	TO DETACH & RENEW REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$)			1,635.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >