## PAR Automotive Consultancy

## Parts and Labour Assessment

Report No: 0040-21-HLm Vehicle No: SMQ7349E

Description of part			Qty	Condition as inspected	Repairer's estimate adj	Our ustment
Front door LH		1	buckled	851.10	851.10	
Front door glass outer moulding LH			1	deformed	Ju 58.00	58.00 ⊀
Front door outer handle LH			1	fractured	/L 85.00	85.00 X
Front door inner lock LH		1	bent	N 233.70	233.70 X	
Front door outer garnish vertical LH		1	necessary	36.00	36.00	
Front door window regulator c/w motor LH		1	bent/shorted	1- 405.30	405.30 🗶	
Front door window channel LH			1	bent	<i>f</i>	68.80 Å
Rear door LH			1	buckled	L-N 865.00	865.00 1501a
Rear door door outer moulding LH		1	necessary	fm 53.30	53.30 🗙	
Rear door checker LH		1	bent	5 74.50	74.50 ⊀	
Rear door inner lock LH		1	bent	A 231.20	231.20 ⊀	
Rear door garnish vetical rear LH			1	necessary	~~ 30.00	30.00 ∧
			Subte	otal before discount	2,991.90	2,991.90
	Percentage discount	0%	and	20%	0.00	598.38
	•			Sub-total 1	2,991.90	2,393.52
Front door speaker LH			1	distortion	Pm 150.00	150.00 X
			Subt	otal before discount	150.00	150.00
	Percentage discount	0%	and	0%	0.00	0.00
				Sub-total 2	150.00	150.00
				Parts-tota	3,141.90	2,543.52
LABOUR  1. To straighten and panel pillar LH and LH frame m LH front and rear door con	embers. To remove, tra				900.00	750.00 409
2. To putty, re-spray painting and polish affected areas.				840.00	660.00 4901	
3. To check and rectify wiring system.				80.00	50.00 20	
4. To rust proof affected areas.					120.00	60.00 30
				Labour tota	1,940.00	1,520.00

## PAR Automotive Consultancy

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is : and the recommended number of working days for the repairs is :

4

\$3,400.00

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser