

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21009364/APA3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210059242
Claimant Vehicle No :	GBC2405M	Insured Vehicle No :	SNA2399R
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	9486488969SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2405M	Engine No:	K9KF276D123920
Make & Model:	NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)	Chassis No:	VSKYBAM20U0024795
Reg. Date:	21/09/2011 (Man. Year: 2011)	Odometer:	111900 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,475.55	3,958.09	517.46	11.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	2,050.00	500.00	19.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,025.55	6,008.09	1,017.46	14.48
Approved Total (Overridden) (S\$)		4,800.00		

(S\$)	7,025.55	4,800.00	2,225.55	31.68
+ GST 7.00/7.00% (S\$)	491.79	336.00	155.79	31.68
Nett Amount (S\$)	7,517.34	5,136.00	2,381.34	31.68
+ Loss of Use (8.0 x S\$65.00/day) (S\$)		520.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,658.00		
Global Sum Settlement (S\$)		5,620.00		

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 07/09/2021

Inspected At:

Modern Automotive Pte Ltd (HQ)
 Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	632.70 FL	*632.70 FL
2	2		*REAR BUMPER SIDE HOLDER-LH & RH	Necessary	70.80 FL	*70.80 FL
3	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	122.00 FL	*- FL
4	1		*REAR BUMPER SPONGE	Cracked	145.20 FL	*145.20 FL
5	1		*REAR END PANEL -OUTER	Dented	366.20 FL	*366.20 FL
6	1		*REAR END PANEL -INNER	Dented	610.80 FL	*610.80 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed	129.10 FL	*129.10 FL
8	1		*TAIL LAMP -LH	Not Necessary	297.40 FL	*- FL
9	1		*REAR DOOR-LH	Dented	1,469.60 FL	*1,469.60 FL
10	1		*REAR DOOR LOWER LOCK -LH	Damaged	135.60 FL	*135.60 FL
11	1		*REAR DOOR WEATHERSTRIP -LH	Cut	136.70 FL	*136.70 FL
12	1		*NISSAN LOGO	Necessary	85.00 FL	*85.00 FL
13	1		*NV200 EMBLEM	Necessary	88.40 FL	*88.40 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
15	2		*REAR BUMPER PROTECTOR -LH & RH	Necessary	100.00 FS	*100.00 FS
16	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
17	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
18	1		*REAR DOOR REFLECTIVE STICKER -LH	Necessary	80.00 FS	*20.00 FS
19	1		*REAR DOOR GLASS SEALANT -LH	Necessary	50.00 FS	*50.00 FS
20	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,904.50	4,345.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	428.95	387.01
Total Parts (\$\$)	4,475.55	3,958.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,200.00	1,000.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	800.00	750.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO TRANSFER DOOR FITTINGS	New	150.00	80.00
7	TO REMOVE REAR DOOR GLASS	New	100.00	60.00
Gross Labour Cost (S\$)			2,550.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >