

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009375/ETF3E2

Date: 10/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700040872
Claimant Vehicle No : SLR3674Z **Insured Vehicle No :** SDT1718D
Date of Loss: 04/09/2021 Nature of Claim: TP Claim No: 1014956471SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR3674Z**
Make & Model: TOYOTA VOXY HYBRID V, 1.8 (A) Engine No: 2ZR1965841
Reg. Date: 11/08/2017 (Man. Year: 2017) Chassis No: ZWR800257728
Colour: Black Odometer: 282479 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Windforce 5 mm Rear Left Side: Windforce 5 mm
Front Right Side: Windforce 5 mm Rear Right Side: Windforce 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/09/2021
Date Inspected: 07/09/2021 Inspected At: ALPHA PERFORMANCE SINGAPORE PTE LTD (HQ)
48 TOH GUAN ROAD EAST, #04-126
ENTERPRISE HUB
Singapore 608586
Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$91,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRT RH DOOR HINGE	Bent	0.00 F	*- F
2	1		*FRT RH DOOR GLASS REGULATOR	* Check	0.00 F	*- F
3	1		*FRT RH DOOR GLASS REGULATOR MOTOR	* Check	0.00 F	*- F
4	1		*FRT RH DOOR RUBBER	Crushed	0.00 F	*- F
5	1		*FRT RH DOOR LOCK	Jammed	0.00 F	*- F
6	1		*FRT RH DOOR GARNISH	Broken	0.00 F	*- F
7	1		*ROCKER PANEL RH	Repair	0.00 F	*- F
8	1		*ROCKER PANEL GARNISH RH	Cut	0.00 F	*- F
9	1		*FRT RH FENDER	Repair	0.00 F	*- F
10	1		*FRT RH FENDER GARNISH	Broken	0.00 F	*- F
11	1		*FRT RH DOOR	Dented	0.00 F	*- F
					F=Franchise part.	
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >