

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/CTI21009384/GTCN2**Date:** 10/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00106752105

**Claimant Vehicle No :** GBG6463Y **Insured Vehicle No :** GBF3038S

Date of Loss: 02/09/2021 Nature of Claim: TP Claim No: SNM21D204973/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG6463Y**

Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: ZD30026171N

Reg. Date: 27/09/2017 (Man. Year: 2016) Chassis No: JN1SC2F24Z0860223

Colour: Blue Odometer: 70061 km

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15 Rear Tyre Size: 155R13

Front Left Side: APLUS 6 mm Rear Left Side: APLUS 6 mm

Front Right Side: APLUS 6 mm Rear Right Side: APLUS 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment: 06/09/2021

Date Inspected: 07/09/2021 Inspected At: Alpha Car Services Pte Ltd (HQ)  
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay  
Singapore 417883

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00  
-\$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 09 Sep 2021)

**Parts:** N/A NISSAN CABSTAR 3.0 (M) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBG6463Y)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**