

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009385/ATCE2

Date: 19/11/2021

REFERENCE

Insured/Claimant: LIM CHIEW LAN Policy No: 2070126274
Date of Loss: 02/09/2021 Nature of Claim: OD Claim No: 4214323824SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU8013X**
Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC34974
Reg. Date: 28/08/2020 (Man. Year: 2019) Chassis No: WAUZZZ8V9LA007302
Colour: Grey Odometer: 10914 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$110,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,559.60	18,744.96	15,814.64	45.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,804.00	9,024.00	6,780.00	42.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,363.60	27,768.96	22,594.64	44.86
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	50,063.60	27,468.96	22,594.64	45.13
+ GST 7.00/7.00% (S\$)	3,504.45	1,922.83	1,581.62	45.13
Nett Amount (S\$)	53,568.05	29,391.79	24,176.26	45.13

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 06/09/2021 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,987.00 FS	*1,589.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	78.00 FS	*- FS
4	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	160.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	536.00 FS	*- FS
6	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Cracked	594.00 FS	*474.40 FS
7	2		*FRONT BUMPER COVER TRIM - LH / RH	Not Necessary	326.00 FS	*- FS
8	2		*FRONT BUMPER ADAPTERE - LH / RH	Not Necessary	76.00 FS	*- FS
9	1		*RADIATOR GRILLE	Smashed	1,406.00 FS	*1,124.80 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Smashed	191.00 FS	*152.40 FS
11	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	376.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT FORM	Cracked	189.00 FS	*151.20 FS
13	1		*FRONT BUMPER REINFORCEMENT	Bent	795.00 FS	*636.00 FS
14	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	122.00 FS	*97.20 FS
15	1		*A/C STICKER	Necessary	8.00 FS	*5.68 FS
16	1		*CAUTION STICKER	Necessary	14.00 FS	*10.88 FS
17	2		*HORN - LH / RH	Not Necessary	400.00 FS	*- FS
18	2		*FRONT FENDER - LH / RH	Buckled	1,702.00 FS	*1,360.80 FS
19	10		*RIVET	Necessary	33.00 FS	*26.40 FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
21	2		*FRONT FENDER TOP BRACKET - FRONT LH / RH	Bent	78.00 FS	*61.44 FS
22	2		*FRONT FENDER TOP BRACKET - REAR LH / RH	Not Necessary	56.00 FS	*- FS
23	2		*FRONT FENDER BRACE - LH / RH	Bent	192.00 FS	*152.96 FS
24	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	338.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	89.00 FS	*- FS
26	1		*FRONT BONNET	Buckled	3,134.00 FS	*2,507.20 FS
27	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
28	2		*FRONT BONNET HINGE - LH / RH	Bent	124.00 FS	*97.76 FS
29	1		*FRONT BONNET CATCH	Bent	90.00 FS	*71.28 FS
30	1		*FRONT BONNET STRIKER - LH / RH	N/S Bent	220.00 FS	*87.60 FS
31	1		*FRONT BONNET EDGE PROTECTION	Necessary	28.00 FS	*22.00 FS
32	1		*FRONT BONNET LOWER CATCH	Bent	63.00 FS	*50.32 FS
33	1		*FRONT BONNET LOCK	N/S Damaged	427.00 FS	*170.80 FS
34	1		*FRONT BONNET BOWDEN CABLE - CENTRE	Not Necessary	58.00 FS	*- FS
35	1		*FRONT BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
36	1		*FRONT BONNET LOCK CABLE	Not Necessary	74.00 FS	*- FS
37	1		*FRONT BONNET SOUND ABSORBER	Not Necessary	219.00 FS	*- FS
38	1		*FRONT PLENUM CHAMBER COVER	Not Necessary	179.00 FS	*- FS
39	2		*HEADLIGHT - LH / RH	Cracked	10,910.00 FS	*8,728.00 FS
40	1		*HEADLIGHT POWER MODULE - LH	Not Necessary	758.00 FS	*- FS
41	1		*HEADLIGHT CONTROL UNIT - LIGHT CONTROL	Not Necessary	557.00 FS	*- FS
42	1		*HEADLIGHT HEAT SINK - LH	Not Necessary	733.00 FS	*- FS
43	2		*HEADLIGHT LIFT CYLINDER - LH / RH	Not Necessary	284.00 FS	*- FS
44	1		*HEADLIGHT LIFT CYLINDER HOSE	Not Necessary	68.00 FS	*- FS
45	1		*FRONT LOCK CARRIER	Cracked	727.00 FS	*581.60 FS
46	1		*CONDENSER	Not Necessary	529.00 FS	*- FS
47	1		*TEMPRETURE SENSOR BRACKET	Not Necessary	19.00 FS	*- FS
48	1		*RADIATOR	Not Necessary	951.00 FS	*- FS
49	1		*ADDITIONAL RADIATOR	Not Necessary	856.00 FS	*- FS
50	1		*RADIATOR FAN	Not Necessary	1,265.00 FS	*- FS
51	1		*COOLANT	Necessary	266.00 FS	*212.64 FS
			(6PCS)			
52	1		*RADIATOR AIR GUIDE - LH / RH / UPPER CENTRE	Torn	62.00 FS	*48.32 FS
			(3PCS)			
53	1		*RADIATOR AIR GUIDE SEAL - RIGHT OUTER	Not Necessary	8.00 FS	*- FS
54	1		*INTAKE AIR DUCT TOP COVER	Not Necessary	29.00 FS	*- FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
55	1		*INTAKE AIR DUCT	Cracked	55.60 FS	*44.48 FS	
56	1		*INTAKE AIR DUCT AIR GUIDE	Not Necessary	20.00 FS	*- FS	
57	1		*WATER DRAINAGE HOSE	Not Necessary	33.00 FS	*- FS	
58	1		*INTAKE AIR DUCT AIR GUIDE HOSE	Not Necessary	66.00 FS	*- FS	
59	2		*RADIATOR BRACKET	Not Necessary	82.00 FS	*- FS	
60	2		*RADIATOR BUSH	Not Necessary	19.00 FS	*- FS	
61	2		*WATER DEFLECTOR STRIP - LH / RH	Not Necessary	186.00 FS	*- FS	
62	2		*FRONT WINDOW SLOT SEAL CHROME TRIM - LH / RH	Not Necessary	618.00 FS	*- FS	
63	1		*FRONT NO. PLATE	Bent	60.00 FS	*60.00 FS	
64	1		*SUNDRIES	Necessary	400.00 FS	*57.60 FS	
65	1		*FAN RING (Supplementary)	Cracked	202.00 F	*161.60 F	
					Total Parts (\$\$)	34,559.60	18,744.96

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,400.00	1,400.00
4	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOORS	New	560.00	280.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,250.00
6	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDERS, HINGES, BOTH UPPER A-PILLAR AND BOTH FRONT DOORS	New	6,800.00	2,850.00
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
			Gross Labour Cost (\$\$)	15,804.00
				9,024.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >