

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21009386/GQF3E2**Date:** 09/11/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001530424
Claimant Vehicle No :	SNA7907S	Insured Vehicle No :	SGA6699G
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	262203

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA7907S	Engine No:	G4FMMU036180
Make & Model:	HYUNDAI CN7 AVANTE 1.6, 1.6 (A)	Chassis No:	KMHLN41ETNU202055
Reg. Date:	14/07/2021 (Man. Year: 2021)	Odometer:	4648 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 9 mm	Rear Left Side:	Kumho 9 mm
Front Right Side:	Kumho 9 mm	Rear Right Side:	Kumho 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,115.20	3,023.60	15,091.60	83.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,450.00	1,390.00	6,060.00	81.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,565.20	4,413.60	21,151.60	82.74
Approved Total (Overridden) (\$\$)		3,500.00		
(\$\$)	25,565.20	3,500.00	22,065.20	86.31
+ GST 7.00/7.00% (\$\$)	1,789.56	245.00	1,544.56	86.31
Nett Amount (\$\$)	27,354.76	3,745.00	23,609.76	86.31

INSPECTION

Date of Assignment:	07/09/2021	
Date Inspected:	07/09/2021	Inspected At: AP Automotive Services Pte Ltd 56 Loyang Way, #04-04 Loyang Enterprise Building Singapore 508775
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Nov 2022)
Parts:	143	HYUNDAI CN7 AVANTE 1.6 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA7907S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	2,023.00 FL	*1,782.00 FL
2	1		*BOOTLID LOGO - HYUNDAI	Necessary	34.00 FL	*34.00 FL
3	1		*BOOTLID EMBLEM - AVANTE	Necessary	32.00 FL	*32.00 FL
4	1		*BOOTLID OUTER GARNISH	Not Necessary	489.00 FL	*- FL
5	2		*BOOTLID LAMP L+R	Not Necessary	2,546.00 FL	*- FL
6	1		*BOOTLID CENTER LAMP	Broken	1,273.00 FL	*1,273.00 FL
7	1		*BOOTLID CENTER LAMP GARNISH	Not Necessary	287.00 FL	*- FL
8	1		*BOOTLID CAMERA	Not Necessary	991.00 FL	*- FL
9	1		*BOOTLID LOCK	Not Necessary	116.00 FL	*- FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	39.00 FL	*- FL
11	1		*BOOTLID INNER TRIM	Torn	161.00 FL	*161.00 FL
12	2		*BOOTLID HINGE L+R	Not Necessary	252.00 FL	*- FL
13	1		*BOOTLID WEATHERSTRIP	Not Necessary	109.00 FL	*- FL
14	2		*TAIL LAMP L+R	Not Necessary	1,752.00 FL	*- FL
15	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	90.00 FL	*- FL
16	2		*TAIL LAMP PANEL L+R	Not Necessary	908.00 FL	*- FL
17	1		*REAR BUMPER	Not Necessary	470.00 FL	*- FL
18	1		*REAR BUMPER CENTER GARNISH (NPA)	Not Necessary	0.00 FL	*- FL
19	2		*REAR BUMPER NUMBER PLATE LAMP L+R	Not Necessary	62.00 FL	*- FL
20	2		*SET REAR BUMPER REVERSE SENSOR	Not Necessary	338.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	404.00 FL	*- FL
22	1		*REAR BUMPER LOWER	Not Necessary	341.00 FL	*- FL
23	2		*REAR BUMPER RETAINER L+R	Not Necessary	58.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT BAR	Cracked	294.00 FL	*294.00 FL
25	1		*REAR BUMPER SPONGE	Not Necessary	136.00 FL	*- FL
26	1		*REAR BUMPER UNDERCOVER	Not Necessary	36.00 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	135.00 FL	*- FL
28	2		*REAR FENDER L+R	Not Necessary	3,778.00 FL	*- FL
29	2		*REAR FENDER INNER TRIM L+R	Not Necessary	598.00 FL	*- FL
30	2		*REAR FENDER COWLING L+R	Not Necessary	178.00 FL	*- FL
31	2		*REAR PROXIMITY SENSOR L+R (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*END PANEL	Repair	456.00 FL	*- FL
33	1		*END PANEL TOP GARNISH	Deformed	91.00 FL	*91.00 FL
34	1		*REAR SMART LOCK ANTENNA	Not Necessary	65.00 FL	*- FL
35	1		*SPARE WHEEL PANEL	Not Necessary	499.00 FL	*- FL
36	1		*SPAREWHEEL PANEL TOP BOARD	Not Necessary	249.00 FL	*- FL
37	1		*EXHAUST PIPE	Not Necessary	391.00 FL	*- FL
38	2		*EXHAUST MOUNTING	Not Necessary	124.00 FL	*- FL
39	1		*EXHAUST HEAT SHIELD	Not Necessary	139.00 FL	*- FL
40	1		*BOOTLID INNER TRIM CLIPS	Necessary	100.00 FS	*30.00 FS
41	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

11/9/22, 2:53 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*TAIL LAMP PANEL SEALANT	Not Necessary	240.00 FS	*- FS
43	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
44	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*40.00 FS
45	2		*REAR FENDER SEALANT	Not Necessary	500.00 FS	*- FS
46	2		*REAR FENDER INNER TRIM CLIPS	Not Necessary	200.00 FS	*- FS
47	2		*REAR FENDER COWLING CLIPS	Not Necessary	200.00 FS	*- FS
48	1		*END PANEL SEALANT	Not Necessary	250.00 FS	*- FS
49	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
50	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					22,104.00	3,757.00
- List Item Discount on L Items 20.00/20.00% (S\$)					3,988.80	733.40
Total Parts (S\$)					18,115.20	3,023.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	600.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,600.00	600.00
3	TO RNR REAR EXHAUST	New	250.00	0.00
4	TO CHECK WIRING AND TAILLAMP FUNCTION }	New	150.00	30.00
5	TO CHECK WIRING AND BOOTLID LAMP FUNCTION }	New	150.00	0.00
6	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO RNR FUEL TANK	New	250.00	0.00
9	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
10	TO RNR REAR BOOTLID MECHANISM	New	350.00	60.00
11	TO RNR REAR DOOR MECHANISM	New	600.00	0.00
12	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	40.00
13	TO PERFORM RUST PROOFING	New	400.00	0.00
Gross Labour Cost (\$\$)			7,450.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >