

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009393/RTCE2

Date: 18/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00020412100
Claimant Vehicle No : SLU8913K Insured Vehicle No : SMZ133J
Date of Loss: 27/08/2021 Nature of Claim: TP Claim No: SNM21D205057/C02/SMZ133J/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8913K**
Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGHU835944
Reg. Date: 18/12/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU593087
Colour: Grey Odometer: 37842 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,406.60	2,230.00	2,176.60	49.39
Miscellaneous Items	280.00	155.00	125.00	44.64
Labour	315.00	315.00	0.00	0.00
Paintwork Labour	414.55	414.55	0.00	0.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,416.15	3,114.55	2,301.60	42.50
+ GST 7.00/7.00% (S\$)	379.13	218.02	161.11	42.49
Nett Amount (S\$)	5,795.28	3,332.57	2,462.71	42.50

INSPECTION

Date of Assignment: 09/09/2021 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected: 07/09/2021 Inspected At: Auto Insure Pte Ltd (HQ) (Woodlands)
6 Marsiling Lane
Singapore 739145
Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 May 2022)
Parts:	143	HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU8913K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		3,916.00 F	*2,140.00 F
<u>Supplementary #1</u>						
2	1		*FRT NO PLATE REINF	Cracked	30.00 F	*30.00 F
3	1		*RAD GRILLE BRACKET	Necessary	60.00 F	*60.00 F
F=Franchise part.						
Sub Total (S\$)					4,006.00	2,230.00
+ Margin on L,N Items 10.00/0.00% (S\$)					400.60	0.00
Total Parts (S\$)					4,406.60	2,230.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	280.00	155.00
Sub Total (\$\$)			280.00	155.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	LABOUR FOR SPRAY PAINTING	New	414.55	414.55
<u>Labour Items</u>				
2	LABOUR FOR PANEL BEATING	New	315.00	315.00
Gross Labour Cost (\$\$)			729.55	729.55

Report was unsubmitted during this print-out.

< END OF ESTIMATES >