

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21009394/T1TF3E2

Date: 29/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070085775		
Claimant Vehicle No :	FBR3464G	Insured Vehicle No :	GBF5545G		
Date of Loss:	31/08/2021	Nature of Claim:	TP	Claim No:	8701941128SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR3464G	Engine No:	H336E0075948
Make & Model:	YAMAHA CZD300A / XMAX300, 292cc	Chassis No:	MH3SH0841LK010040
Reg. Date:	04/05/2020 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	292 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	140/70 R14
Front Left Side:	MITAS 5 mm	Rear Left Side:	MITAS 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	07/09/2021		
Date Inspected:	07/09/2021	Inspected At:	Equator Brotherhood (HQ) 25 kaki bukit rd 4 #03-79 synergy @ kb Singapore 417800
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$22,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER WHEEL GUARD	Cut	0.00 F	*- F
2	1		*FRONT FORK ASSY	* Check	0.00 F	*- F
3	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
4	1		*HANDLE BAR	* Check	0.00 F	*- F
5	1		*HANDLE BAR GRIP	Torn	0.00 F	*- F
6	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
7	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
8	1		*SIDE FAIRING TOP GARNISH BLUE	Cut	0.00 F	*- F
9	1		*SIDE FAIRING LOWER GARNISH BLACK	Cut	0.00 F	*- F
10	1		*CENTER FAIRING	Cut	0.00 F	*- F
11	1		*REAR FAIRING LH	Cut	0.00 F	*- F
12	1		*WINDSHIELD SIDE GARNISH LH	Cut	0.00 F	*- F
13	1		*STEP GARNISH LH	Cut	0.00 F	*- F
14	1		*STEP GARNISH RUBBER LH	Cut	0.00 F	*- F
15	1		*STEP PANEL LOWER GARNISH	Cut	0.00 F	*- F
16	1		*SEAT ASSY COVER	Torn	0.00 F	*- F
17	1		*SIDE STAND	Dented	0.00 F	*- F
18	1		*MAIN STAND	Bent	0.00 F	*- F
19	1		*REAR FOOT REST	Cut	0.00 F	*- F
20	1		*REAR FENDER WHEEL GUARD	Deformed	0.00 F	*- F
21	1		*REAR FENDER MUDFLAP	Cut	0.00 F	*- F
22	1		*REAR TAILLAMP RH	Cut	0.00 F	*- F
23	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
24	1		*EMBLEM	Necessary	0.00 F	*- F
25	1		*AIR FILTER BOX	Cut	0.00 F	*- F
26	1		*AIR FILTER AIR GRILLE	Cut	0.00 F	*- F
27	1		*PILLION HANDLE GRIP	Cut	0.00 F	*- F
28	1		*REAR SEAT EMBLEM	Cut	0.00 F	*- F
29	1		*REAR SEAT CENTRE GARNISH	Cut	0.00 F	*- F
30	1		*REAR FAIRING LOWER GARNISH	Cut	0.00 F	*- F
31	1		*REAR LOWER CENTRE GARNISH	Cut	0.00 F	*- F
F=Franchise part.						
					Total Parts (\$\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >