



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 8969K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR WINDSCREEN MOULDING UPPER	SERVICEABLE	35.50	-
1	REAR WINDSCREEN MOULDING LOWER	SERVICEABLE	155.00	-
1	REAR WINDSCREEN MOULDING LH	SERVICEABLE	45.00	-
1	REAR WINDSCREEN MOULDING RH	SERVICEABLE	45.00	-
1	REAR BUMPER	BENT	777.90	777.90
10	REAR BUMPER CLIP	NECESSARY	35.00	35.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	27.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	27.50	-
1	REAR BUMPER LH	BUCKLED / DISTORTED	195.00	195.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	161.00	-
1	TAIL DOOR	TO REPAIR SEE LABOUR	1,250.00	-
1	TAIL DOOR LOCK	TO REPAIR SEE LABOUR	187.10	-
1	TAIL DOOR EMBLEM	NOT NECESSARY	35.70	-
1	WORDING "VEZEL"	NECESSARY	58.00	58.00
1	WORDING "HYBRID"	NECESSARY	60.50	60.50
1	BOOTLID REFLECTOR LH	SERVICEABLE	389.20	-
1	LH REAR FENDER PROTECTOR	SERVICEABLE	198.00	-
10	LH REAR FENDER PROTECTOR CLIP	NOT NECESSARY	35.00	-
	LESS 20% DISCOUNT		-743.58	-225.28
			2,974.32	901.12
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
			250.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,TAILDOOR,END PANEL,LHR FENDER,SPARE TYRE WELL PANEL).INCLUSIVE OF THE REPAIR OF TAIL DOOR AND TAIL DOOR LOCK.		1,200.00	500.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(REAR BUMPER,TAILDOOR,END PANEL,LHR FENDER,SPARE TYRE WELL PANEL).		1,200.00	520.00
	TO REMOVE & REFIT SPARE TYRE,SPARE TYRE BOARD,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO TUFF COAT.	NOT NECESSARY	150.00	-
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.	NOT NECESSARY	120.00	-
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
			3,230.00	1,110.00
<b>GRAND TOTAL</b>			<b>6,454.32</b>	<b>2,011.12</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CS/AGI21009399/Kvf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.