

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3881K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	HONDA & FIT EMBLEM	NECESSARY	120.00	88.80
2	REVERSE SENSOR	NOT NECESSARY	480.00	-
1	REVERSE CAMERA	NOT NECESSARY	180.00	-
1	REPLACE NEW REAR BOOT	BUCKLED	1,600.00	779.00
1	REAR NEW WINDSCREEN	CRACKED	1,280.00	1,050.00
1	REPLACE NEW REAR BUMPER	DEFORMED	1,800.00	575.00
1	REAR DOOR LOCKING SYSTEM	NOT NECESSARY	480.00	-
2	REAR DOOR ABSORBER HINGE	NOT NECESSARY	400.00	-
1	WEATHER STRIP	NOT NECESSARY	280.00	-
1	TAILGATE OUTER GARNISH NEW	CRACKED	450.00	250.00
1	LOWER BUMPER SPOILER	NOT NECESSARY	380.00	-
1	REAR REINFORCEMENT	NOT NECESSARY	980.00	-
	LESS 20% DISCOUNT		-	-548.56
			8,430.00	2,194.24
	<u>LABOUR</u>			
	LABOUR FOR REMOVE AND INSTALLATION OF DAMAGED & AFFECTED PARTS REAR BUMPER AND REAR BOOT AND WINDSCREEN & NECESSARY PARTS.		950.00	500.00
	SPRAY PAINTING TO REAR BUMPER,REAR BOOT & TAILGATE OUTER GARNISH & NECESSARY PARTS.		850.00	450.00
	DIAGNOSTIC TO VEHICLE & ELECTRICAL SYSTEM.		250.00	30.00
	REWIRING OF CAMERA.		220.00	30.00
			2,270.00	1,010.00
	GRAND TOTAL		10,700.00	3,204.24
	RECOMMENDED COST OF LUMP SUM REPAIRS			2.550.00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,550.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR21009404/Gqf3n2

XING GUO QIANG

M.MATAI, AMSAE-A

P

ANG BRYAN TANI

Automotive Assessor / Investigator

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.