

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009412/UVCN2**Date:** 24/09/2021**REFERENCE**

|                              |   |                             |                        |
|------------------------------|---|-----------------------------|------------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMPCSNW00161842100     |
| <b>Claimant Vehicle No :</b> | GX6470C                                       | <b>Insured Vehicle No :</b> | SKS6166K               |
| Date of Loss:                | 01/09/2021                                    | Nature of Claim:            | TP                     |
|                              |   | Claim No:                   | SNM21D204968/C02/TANKL |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>GX6470C</b>                    | Engine No:  | 5L5443729         |
| Make & Model:               | TOYOTA DYNA 150 D, 3.0 D (M)      | Chassis No: | JTFUF34Y403002566 |
| Reg. Date:                  | 03/08/2004 (Man. Year: 2004)      | Odometer:   | 214603 km         |
| Colour:                     | Silver                            |             |                   |
| Engine Capacity:            | 2986 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |                 |
|-------------------|---------------|------------------|-----------------|
| Front Tyre Size:  | 185 R14       | Rear Tyre Size:  | 155 R12(D)      |
| Front Left Side:  | Habilead 6 mm | Rear Left Side:  | Habilead 6/6 mm |
| Front Right Side: | Habilead 6 mm | Rear Right Side: | Habilead 6/6 mm |

*The above values represent the remaining tyre tread depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 3,301.84          | 1,247.04          | 2,054.80          | 62.23         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,100.00          | 800.00            | 1,300.00          | 61.90         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>5,401.84</b>   | <b>2,047.04</b>   | <b>3,354.80</b>   | <b>62.10</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>1,600.00</b>   |                   |               |
| <b>Nett Amount (\$\$)</b>                 | <b>5,401.84</b>   | <b>1,600.00</b>   | <b>3,801.84</b>   | <b>70.38</b>  |

**INSPECTION**

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 07/09/2021               | Tick Hai Motor & Welding Services - Kaki Bukit (HQ) |
| Date Inspected:             | 20/09/2021 Inspected At: | BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT |
| Estimated Period of Repair: | 3.0 days                 | Singapore 417883                                    |

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |  |   |
|----------------------|--|---|
| <b>Part Source:</b>  | (Last Synchronised: 24 Sep 2021)   |   |
| <b>Parts:</b>        | N/A  | TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database) |
| <b>Labour:</b>       | Repairer's   | (Price-denominated Standard List)                             |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GX6470C)   |   |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |   |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.   |   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                   | Condition         | Repairer's   | Amount          |
|-----|-----|----------|-------------------------------|-------------------|--|-----------------|
| 1   | 1   |          | *HEADLAMP O/S                 | Scratched/Cracked | 1,214.48 FL  | *645.30 FL      |
| 2   | 1   |          | *FRONT BUMPER                 | Distorted         | 375.40 FL  | *375.40 FL      |
| 3   | 1   |          | *FRONT GRILLE                 | Cracked           | 448.69 FL  | *448.69 FL      |
| 4   | 1   |          | *FRONT DOOR O/S               | Repair            | 1,487.80 FL  | *- FL           |
| 5   | 1   |          | *FRONT DOOR WEATHERSTRIP O/S  | Not Necessary     | 195.60 FL  | *- FL           |
| 6   | 1   |          | *STEP GARNISH O/S             | Serviceable       | 287.40 FL  | *- FL           |
| 7   | 1   |          | *FRONT CORNER PANEL O/S       | Not Necessary     | 199.75 FL  | *- FL           |
| 8   | 1   |          | *SET ROC STICKER O/S          | Necessary         | 25.00 FS   | *25.00 FS       |
| 9   | 1   |          | *SET DOOR COMPANY STICKER O/S | Necessary         | 120.00 FS  | *120.00 FS      |
|     |     |          |                               |                   | <b>Sub Total (\$\$)</b>                                    | <b>4,354.12</b> |
|     |     |          |                               |                   | <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>1,052.28</b> |
|     |     |          |                               |                   | <b>Total Parts (\$\$)</b>                                  | <b>3,301.84</b> |
|     |     |          |                               |                   |  | <b>1,247.04</b> |

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount        |
|--------------------------------|---|----------|-----------------|---------------|
| <b>Labour Items</b>            |   |          |                 |               |
| 1                              | TO CHECK FRONT ELECTRICAL WIRING SYSTEM                                 | New      | 50.00           | 20.00         |
| 2                              | TO TRANSFER DOOR COMPONENTS FROM OLD DOOR TO NEW DOOR                   | New      | 120.00          | 0.00          |
| 3                              | TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS | New      | 950.00          | 300.00        |
| 4                              | TO SPRAY PAINTING ON AFFECTED AREA                                      | New      | 980.00          | 480.00        |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>2,100.00</b> | <b>800.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >