

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009417/ATCN2**Date:** 26/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00106232001

Claimant Vehicle No : SKT5212L**Insured Vehicle No :** GBF4469A

Date of Loss: 30/08/2021

Nature of Claim: TP

Claim No: SNM21D204940/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKT5212L**

Make & Model: MERCEDES-BENZ E200, 1.8 CGI (A)

Engine No: 27186030192111

Reg. Date: 16/06/2011 (Man. Year: 2010)

Chassis No: WDD2120482A391115

Colour: Blue

Odometer: 146890 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R17

Rear Tyre Size: 245/45R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	84,417.20	47,085.90	37,331.30	44.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,550.00	8,890.00	11,660.00	56.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	104,967.20	55,975.90	48,991.30	46.67
Approved Total (Overridden) (\$\$)		39,500.00		
Nett Amount (\$\$)	104,967.20	39,500.00	65,467.20	62.37

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 08/09/2021

Inspected At:

1 KAKI BUKIT AVE 6 #01-27/01-45

SINGAPORE 417883

REPAIRER: CN MOTORS PTE LTD

Estimated Period of Repair: 28.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2021)
Parts:	143	MERCEDES-BENZ E200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT5212L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,695.00 FL	*1,559.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	608.00 FL	*608.00 FL
3	2		*FRONT BUMPER REINFORCEMENT SIDE BRACKET	Bent	242.00 FL	*242.00 FL
4	2		*FRONT BUMPER BRACKET	Damaged	90.00 FL	*90.00 FL
5	2		*FRONT BUMPER SIDE RETAINER	Damaged	130.00 FL	*130.00 FL
6	1		*FRONT BUMPER CENTER SPONGE	Cracked	118.00 FL	*118.00 FL
7	2		*FRONT BUMPER SIDE SPONGE	Cracked	118.00 FL	*118.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Cracked	132.00 FL	*132.00 FL
9	1		*FRONT BUMPER TOW COVER	Damaged	45.00 FL	*45.00 FL
10	1		*FRONT BUMPER NUMBER PLATE GARNISH	Deformed	85.00 FL	*85.00 FL
11	1		*FRONT BUMPER FOG LAMP	N/s Smashed	448.00 FL	*224.00 FL
12	1		*FRONT BUMPER FOG LAMP OUTER GARNISH	N/s Deformed	152.00 FL	*76.00 FL
13	1		*FRONT BUMPER FOG LAMP OUTER GARNISH CHROME	N/s Cut	132.00 FL	*66.00 FL
14	1		*FRONT BUMPER FOG LAMP WIRE HARNESS	Not Necessary	265.00 FL	*- FL
15	2		*FRONT BUMPER LOWER CHROME	Damaged	112.00 FL	*112.00 FL
16	1		*FRONT BUMPER SENSOR (4 Pcs)	Damaged (3 Pcs only)	992.00 FL	*744.00 FL
17	4		*FRONT BUMPER SENSOR BRACKET	Necessary	184.00 FL	*80.00 FL
18	1		*FRONT BUMPER SENSOR WIRE HARNESS	Cut	648.00 FL	*325.00 FL
19	1		*FRONT BUMPER SENSOR ECU	Not Necessary	954.00 FL	*- FL
20	1		*FRONT BUMPER CENTER BRACKET	Distorted	68.00 FL	*68.00 FL
21	1		*FRONT BUMPER UNDER COVER	Torn	285.00 FL	*285.00 FL
22	1		*FRONT SUPPORT PANEL TOP	Distorted	585.00 FL	*585.00 FL
23	2		*FRONT SIDE SUPPORT PANEL	Distorted	474.00 FL	*474.00 FL
24	1		*FRONT SUPPORT PANEL TOP COVER	Distorted	216.00 FL	*216.00 FL
25	2		*FRONT SUPPORT PANEL BRACKET	Distorted	130.00 FL	*130.00 FL
26	1		*FRONT AIR BAG SENSOR	Activated	240.00 FL	*240.00 FL
27	1		*BONNET	Dispensed	2,502.00 FL	*2,421.00 FL
28	1		*BONNET LOGO	Necessary	103.00 FL	*103.00 FL
29	1		*BONNET LOCK TOP	Jammed	60.00 FL	*60.00 FL
30	2		*BONNET LOCK SIDE BOTTOM	Jammed	230.00 FL	*230.00 FL
31	1		*BONNET LOCK CENTER LEVEL	Damaged	48.00 FL	*48.00 FL
32	1		*BONNET LOCK CATCH	Bent	43.00 FL	*43.00 FL
33	1		*BONNET INSULATOR	Not Necessary	165.00 FL	*- FL
34	2		*BONNET LOCK SPRING	Damaged	64.00 FL	*64.00 FL
35	2		*BONNET HINGE	Bent	290.00 FL	*290.00 FL
36	2		*BONNET HINGE ACTUATOR	Not Necessary	824.00 FL	*- FL
37	2		*BONNET ABSORBER	Damaged	276.00 FL	*276.00 FL
38	2		*BONNET STOPPED	Necessary	40.00 FL	*40.00 FL
39	2		*FRONT HEADLAMP	N/s Smashed/O/s Cracked	2,562.00 FL	*2,562.00 FL
40	1		*FRONT HEADLAMP WIRE HARNESS	Not Necessary	836.00 FL	*- FL
41	2		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	308.00 FL	*- FL
42	1		*FRONT GRILLE	Cracked	1,235.00 FL	*1,183.00 FL
43	1		*FRONT GRILLE BRACKET	Cracked	156.00 FL	*156.00 FL
44	1		*AIR HORN	N/s Cracked	244.00 FL	*122.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT INTER COOLER	Cracked	1,450.00 FL	*1,450.00 FL
46	1		*FRONT INTER COOLER HOSE LH	Cut	128.00 FL	*128.00 FL
47	2		*FRONT INTER COOLER OUTER GARNISH	Not Necessary	138.00 FL	*- FL
48	1		*FRONT INTER COOLER HOSE RH	Cut	109.00 FL	*109.00 FL
49	1		*RADIATOR	Warped	1,435.00 FL	*1,435.00 FL
50	1		*RADIATOR FAN MOTOR ASSY	Cracked	1,025.00 FL	*1,025.00 FL
51	1		*RADIATOR TOP HOSE	Cut	78.00 FL	*78.00 FL
52	1		*RADIATOR BOTTOM HOSE	Cut	91.00 FL	*91.00 FL
53	1		*AIR CON CONDENSER	Warped	1,287.00 FL	*1,287.00 FL
54	1		*AIR CON CONDENSER PIPING INLET	Bent	314.00 FL	*314.00 FL
55	1		*AIR CON CONDENSER PIPING OUTLET	Bent	351.00 FL	*351.00 FL
56	1		*WIPER TANK	Distorted	128.00 FL	*128.00 FL
57	1		*WIPER TANK MOTOR	Damaged	168.00 FL	*168.00 FL
58	2		*FRONT FENDER	Distorted	2,164.00 FL	*2,164.00 FL
59	2		*FRONT FENDER INNER SHIELD	Torn	370.00 FL	*370.00 FL
60	2		*FRONT FENDER CHROME MOULDING	Necessary	112.00 FL	*112.00 FL
61	2		*FRONT FENDER INNER PANEL	Repair	1,196.00 FL	*- FL
62	2		*FRONT FENDER EMBLEM	Necessary	116.00 FL	*116.00 FL
63	2		*FRONT WHEEL HOUSE PANEL	Repair	2,482.00 FL	*- FL
64	1		*FRONT DOOR LH	Repair	1,998.00 FL	*- FL
65	1		*FRONT DOOR WEATHER STRIPE LH	Not Necessary	237.00 FL	*- FL
66	1		*FRONT DOOR HINGE LH	Not Necessary	248.00 FL	*- FL
67	1		*FRONT DOOR CHECKER LH	Not Necessary	98.00 FL	*- FL
68	1		*LH FRONT WIND MIRROR	Not Necessary	1,056.00 FL	*- FL
69	1		*LH FRONT WIND MIRROR COVER	Not Necessary	394.00 FL	*- FL
70	1		*AUTO TRANSMISSION PIPING INLET	Not Necessary	249.00 FL	*- FL
71	1		*AUTO TRANSMISSION PIPING OUTLET	Not Necessary	254.00 FL	*- FL
72	1		*ABS PUMP	Not Necessary	2,395.00 FL	*- FL
73	1		*ABS PIPING	Not Necessary	458.00 FL	*- FL
74	1		*AIR DUCT	Not Necessary	254.00 FL	*- FL
75	1		*RADIATOR TOP HOSE	Repeated	69.00 FL	*- FL
76	1		*RADIATOR BOTTOM HOSE	Repeated	78.00 FL	*- FL
77	1		*POWER STEERING PUMP	Not Necessary	1,510.00 FL	*- FL
78	1		*POWER STEERING PUMP PIPING	Not Necessary	289.00 FL	*- FL
79	1		*ENGINE COMPARTMENT PANEL TOP RUBBER	Not Necessary	345.00 FL	*- FL
80	1		*ENGINE COMPARTMENT HEAT SHIELD	Not Necessary	141.00 FL	*- FL
81	1		*ENGINE COMPARTMENT INSULATOR	Not Necessary	195.00 FL	*- FL
82	2		*ENGINE MOUNTING	Damaged	578.00 FL	*578.00 FL
83	1		*FRONT SHOCK ABSORBER	N/s Bent	910.00 FL	*455.00 FL
84	1		*FRONT LOWER ARM	N/s Bent	944.00 FL	*472.00 FL
85	1		*FRONT KNUCKLE ARM	N/s Damaged	2,410.00 FL	*1,205.00 FL
86	1		*FRONT KNUCKLE ARM BEARING	N/s Damaged	596.00 FL	*298.00 FL
87	1		*STEERING RACK & PINION	Bent	4,955.00 FL	*4,955.00 FL
88	1		*FRONT STABILISER BAR	Bent	397.00 FL	*397.00 FL
89	1		*FRONT STABILISER LINK	N/s Bent	310.00 FL	*155.00 FL
90	1		*FRONT ABS SENSOR	N/s Damaged	778.00 FL	*389.00 FL
91	2		*FRONT BRAKE CALIPER	Not Necessary	2,220.00 FL	*- FL
92	2		*FRONT BRAKE ROTOR DISC	Not Necessary	558.00 FL	*- FL
93	1		*FRONT CONTROL ARM	N/s Bent	588.00 FL	*294.00 FL
94	1		*FRONT CROSSMEMBER	Bent	1,245.00 FL	*1,245.00 FL
95	1		*FAN BELT	Cut	65.00 FL	*65.00 FL
96	1		*FRONT WIPER GARNISH	Not Necessary	352.00 FL	*- FL
97	2		*ROOF MOULDING	Not Necessary	250.00 FL	*- FL
98	1		*FRONT WINDSCREEN GLASS	Cracked	1,341.00 FL	*1,341.00 FL
99	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	278.00 FL	*278.00 FL
100	1		*AIR BAG LH	Activated	1,132.00 FL	*1,132.00 FL
101	1		*STEERING AIR BAG	Activated	1,435.00 FL	*1,435.00 FL
102	1		*AIR BAG ECU	Activated	521.00 FL	*521.00 FL
103	1		*FRONT DASHBOARD	Torn	2,650.00 FL	*2,650.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
104	2		*FRONT SAFETY BELT WITH BUCKLER	Activated	1,480.00 FL	*1,480.00 FL
105	2		*REAR SAFETY BELT WITH BUCKLER	Not Necessary	2,696.00 FL	*- FL
106	1		*REAR BUMPER	Deformed	1,348.00 FL	*1,348.00 FL
107	1		*REAR BUMPER SIDE RETAINER	O/s Damaged	136.00 FL	*68.00 FL
108	2		*REAR BUMPER CHROME MOULDING	Necessary	490.00 FL	*490.00 FL
109	1		*REAR FENDER RH	Distorted	2,014.00 FL	*2,014.00 FL
110	1		*REAR FENDER INNER SHIELD	Not Necessary	172.00 FL	*- FL
111	1		*REAR FUEL FLAP	Dented	148.00 FL	*148.00 FL
112	1		*REAR FUEL FLAP SWITCH	Not Necessary	89.00 FL	*- FL
113	1		*REAR FUEL FLAP INNER GARNISH	Cracked	94.00 FL	*94.00 FL
114	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	198.00 FL	*198.00 FL
115	1		*REAR TAILLAMP RH	Not Necessary	598.00 FL	*- FL
116	1		*REAR TAILLAMP LOWER BRACKET RH	Not Necessary	80.00 FL	*- FL
117	1		*ENGINE UNDER COVER	Not Necessary	342.00 FL	*- FL
118	1		*RH REAR DOOR	Repair	2,065.00 FL	*- FL
119	1		*RH REAR DOOR WEATHER STRIPE	Not Necessary	248.00 FL	*- FL
120	1		*RH REAR DOOR CHROME MOULDING	Not Necessary	165.00 FL	*- FL
121	1		*FRONT GRILLE	Repeated	676.00 FL	*- FL
122	1		*RH REAR SHOCK ABSORBER	Not Necessary	603.00 FL	*- FL
123	1		*RH REAR UPPER ARM	Not Necessary	195.00 FL	*- FL
124	1		*RH REAR LOWER ARM	Not Necessary	245.00 FL	*- FL
125	1		*RH REAR KNUCKLE ARM	Not Necessary	1,802.00 FL	*- FL
126	1		*RH REAR KNUCKLE ARM BEARING	Not Necessary	293.00 FL	*- FL
127	1		*REAR BUMPER	Repeated	1,660.00 FL	*- FL
128	1		*REAR BUMPER SIDE RETAINER RH	Repeated	44.00 FL	*- FL
129	1		*AIR CON COMPRESSOR	Cracked	1,185.00 FL	*1,185.00 FL
130	1		*INTAKE MANIFOLD	Cracked	585.00 FL	*585.00 FL
131	4		*LH FRONT TYRE	Frt N/s Punctured/Frt O/s Cut	1,680.00 FS	*400.00 FS
132	1		*ERP BRACKET	Necessary	30.00 FS	*30.00 FS
133	1		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
134	1		*FRONT GRILLE CLIPS	Necessary	60.00 FS	*20.00 FS
135	1		*FRONT WINDSCREEN GLASS SEALANT	Necessary	160.00 FS	*60.00 FS
136	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	160.00 FS	*60.00 FS
137	1		*BOTH FRONT CHASSIS FRAME SEALANT	Necessary	150.00 FS	*100.00 FS
138	1		*LH FRONT FENDER INNER PANEL SEALANT	Not Necessary	150.00 FS	*- FS
139	1		*LH FRONT WHEEL HOUSE PANEL SEALANT	Not Necessary	150.00 FS	*- FS
140	1		*AIR CON GAS	Necessary	120.00 FS	*50.00 FS
141	1		*BRAKE FLUIDE	Necessary	80.00 FS	*40.00 FS
142	1		*POWER STEERING OIL	Necessary	80.00 FS	*40.00 FS
143	4		*RADIATOR TOP/BOTTOM HOSE CLIPS	Necessary	60.00 FS	*20.00 FS
144	6		*POWER STEERING HOSE CLIPS	Not Necessary	40.00 FS	*- FS
145	4		*INTER COOLER PIPING CLIPS	Not Necessary	40.00 FS	*- FS
146	2		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*60.00 FS
147	1		*FRONT BUMPER UNDER COVER CLIPS	Necessary	60.00 FS	*30.00 FS
148	1		*FRONT ENGINE UNDER COVER CLIPS	Not Necessary	60.00 FS	*- FS
149	1		*FRONT NUMBER PLATE WITH CASING	Damaged	60.00 FS	*60.00 FS
150	1		*BONNET INSULATOR CLIPS	Necessary	40.00 FS	*30.00 FS
151	1		*FRONT RIM (4 Pcs)	3 Rim Cut	3,060.00 FS	*1,800.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 93,088.00 52,001.00
- List Item Discount on L Items 10.00/10.00% (\$\$) 8,670.80 4,915.10

Total Parts (\$\$) 84,417.20 47,085.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	6,000.00	2,500.00
2	LABOUR FOR SPRAYPAINTING	New	3,500.00	2,000.00
3	LABOUR FOR REMOVE & RENEW FRONT EXHAUST PIPING,TO REPAIR STRAIGHTEN FRONT EXHAUST PIPE	New	400.00	0.00
4	LABOUR FOR REMOVE & REFIX FRONT ENGINE & GEAR BOX	New	1,000.00	580.00
5	LABOUR FOR REMOVE & RENEW FRONT & REAR UNDER CARRIAGE	New	1,200.00	650.00
6	TO CONDUCT ALL WHEEL ALIGNMENT	New	300.00	80.00
7	LABOUR FOR REMOVE & RENEW FRONT DASHBOARD AIR BAG/STEERING AIR BAG/AIR BAG ECU	New	800.00	550.00
8	LABOUR FOR REMOVE & RENEW ALL SAFETY BELT & BUCKLER	New	600.00	150.00
9	LABOUR FOR REMOVE/RENEW & REFIX UPHOLSTERY/FRONT & REAR CARPET/GARNISH/TRIM BOARD	New	800.00	80.00
10	TO DIAGNOR/RESET/TROUBLE SHOOT ALL WARNING LIGHT	New	800.00	200.00
11	TOW FEE	New	250.00	120.00
12	LABOUR FOR REMOVE & RENEW AIR CON COMPRESSOR,TO VACUUM & TOP UP AIR CON GAS	New	300.00	160.00
13	LABOUR FOR REMOVE & RENEW FRONT DASHBOARD	New	500.00	0.00
14	LABOUR FOR REMOVE & RENEW ABS PUMP/PIPING/TO TOP UP BRAKE FLUID/BLEEDE ALL BRAKE SYSTEM	New	400.00	150.00
15	LABOUR FOR REMOVE & RENEW POWER STEERING PUMP/STEERING RACK & PINION TO TOP UP STEERING OIL	New	400.00	150.00
16	LABOUR FOR REMOVE & RENEW ALL ENGINE MOUNTING/ENGINE MANIFOLD/THROTTLE BODY	New	400.00	200.00
17	LABOUR FOR REPAIR & STRAIGHTEN BOTH FRONT CHASSIS FRAME	New	1,200.00	600.00
18	LABOUR FOR REMOVE & VACUUM/REFILL/REFIX REAR FUEL TANK	New	300.00	80.00
19	LABOUR FOR REMOVE & RENEW FRONT/REAR WINDSCREEN GLASS	New	500.00	240.00
20	WIRING CHECK/TO REMOVE & RENEW FRONT WIRE FUSE BOX	New	300.00	150.00
21	TO APPLY RUST PROOF/TUFF COAT ON ACCIDENT AREAS	New	600.00	250.00
Gross Labour Cost (\$\$)			20,550.00	8,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >