

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009422/R1QCN2**Date:** 20/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00069892103

Claimant Vehicle No : SMZ7011G **Insured Vehicle No :** YP2886S

Date of Loss: 06/09/2021 Nature of Claim: TP Claim No: SNM21D205021/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ7011G**

Make & Model: LAND ROVER RANGE ROVER VELAR, 2.0 P Si4 S/R (A) Engine No: 201009Y0085PT204

Reg. Date: 12/05/2021 (Man. Year: 2020) Chassis No: SALYA2AX4LA293948

Colour: White Odometer: 5636 km

Engine Capacity: 1997 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 255/50R20 Rear Tyre Size: 255/50R20

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,791.05	10,112.13	3,678.92	26.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,701.00	8,801.00	2,900.00	24.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,492.05	18,913.13	6,578.92	25.81
+ GST 7.00/7.00% (S\$)	1,784.44	1,323.92	460.52	25.81
Nett Amount (S\$)	27,276.49	20,237.05	7,039.44	25.81

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 08/09/2021 Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)
28 Leng Kee Road
Singapore 159105

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2022)

Parts: M1-SUV LAND ROVER RANGE ROVER VELAR 2.0 P Si4 S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ7011G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL-BODY SIDE	Buckled	2,682.60 FS	*2,414.34 FS
2	1		*GLASS-QUARTER WIND	Necessary	813.50 FS	*732.15 FS
3	2		*ADHESIVE AND SEALER	Necessary	319.00 FS	*287.10 FS
4	1		**D* PRIMER GLASS & P	Necessary	43.30 FS	*38.97 FS
5	1		*FILLER CAP AND WARNI	Repair	44.60 FS	*- FS
6	1		*HOUSING-FUEL TANK	Cut	330.10 FS	*297.09 FS
7	1		*DOOR-REAR-LESS H	Buckled	3,142.50 FS	*2,828.25 FS
8	1		*SEAL-DOOR FRONT AN	Necessary	194.80 FS	*175.32 FS
9	1		*SEAL-DOOR FRONT AN	Necessary	161.40 FS	*145.26 FS
10	1		*MOULDING-DOOR OUTS	Not Necessary	301.60 FS	*- FS
11	1		*MOULDING-REAR WHEE	Necessary	109.50 FS	*98.55 FS
12	1		*DOOR-REAR WHEEL ARC	Scratched	194.80 FS	*175.32 FS
13	1		*HANDLE-DOOR-OUTE	Not Necessary	411.40 FS	*- FS
14	1		*HANDLE-COVER	Not Necessary	56.50 FS	*- FS
15	1		*LATCH-REAR DOOR	Not Necessary	406.00 FS	*- FS
16	1		*COVER-LATCH	Not Necessary	76.60 FS	*- FS
17	1		*COVER-LATCH SIDE	Not Necessary	76.60 FS	*- FS
18	1		*SHIELD-SPLASH-WH	Deformed	405.90 FS	*365.31 FS
19	1		*FINISHER-OUTER-P	Not Necessary	143.20 FS	*- FS
20	1		*FINISHER-OUTER-P	Not Necessary	125.70 FS	*- FS
21	1		*MOULDING-DOOR WIND	Scratched	199.80 FS	*179.82 FS
22	1		*3M07333 IMPACT RESIS	Necessary	84.10 FS	*75.69 FS
23	1		*3M08115 PANEL BONDIN	Necessary	68.30 FS	*61.47 FS
24	2		*SOUND DEADENING PAD	Necessary	1,156.00 FS	*1,040.40 FS
25	1		*2-PART FLEXIBLE FOAM	Necessary	200.00 FS	*180.00 FS
26	1		*BODY PANEL SEALANT X	Not Necessary	955.20 FS	*- FS
27	1		*ADHESIVE SEALER FL2	Necessary	709.60 FS	*638.64 FS
28	1		*FINISHER-OUTER-Q	Scratched	92.16 FS	*92.16 FS
29	10		*BUMPER NUT XF	Necessary	42.30 FS	*42.30 FS
30	1		*RIVET (25 Pcs)	Necessary	42.75 FS	*42.75 FS
31	4		*RIVET	Necessary	6.84 FS	*6.84 FS
32	2		*RIVET	Necessary	4.50 FS	*4.50 FS
33	2		*RIVET	Necessary	0.90 FS	*0.90 FS
34	1		*RIVET (25 Pcs)	Necessary	36.00 FS	*36.00 FS
35	4		*RIVET	Necessary	9.00 FS	*9.00 FS
36	6		*RIVET	Necessary	10.26 FS	*10.26 FS
37	2		*RIVET	Necessary	6.30 FS	*6.30 FS
38	3		*RIVET	Necessary	9.45 FS	*9.45 FS
39	8		*RIVET-BLIND	Necessary	29.52 FS	*29.52 FS
40	2		*RIVET	Necessary	21.06 FS	*21.06 FS
41	1		**D* WELDING PRIMER	Necessary	67.41 FS	*67.41 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)

13,791.05

10,112.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR FENDER RH,REAR RH DOOR,ETC	New	5,000.00	3,500.00
2	TO SPRAYPAINT ON REAR FENDER RH,RH REAR DOOR,ETC	New	2,700.00	1,800.00
3	TO REPLACE REAR RH QTR GLASS	New	600.00	600.00
4	TO INSTALL REAR RH QTR GLASS F	New	280.00	280.00
5	TO REMOVE,REFIT INTERIOR TRIM CARPET LINING,REAR SEATS	New	2,000.00	1,500.00
6	TO REMOVE,REFIT & TRANSFER REAR RH DOOR PARTS	New	500.00	500.00
7	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
Gross Labour Cost (\$)			11,701.00	8,801.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >