

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009424/DQCE2

Date: 22/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00017692100
Claimant Vehicle No: SLS9061Y Insured Vehicle No: SGX6123E
Date of Loss: 03/09/2021 Nature of Claim: TP Claim No: SNM21D205020/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS9061Y
Make & Model: TOYOTA C-HR HYBRID, 1.8 E G CVT (A) Engine No: 2ZR8003857
Reg. Date: 10/10/2017 (Man. Year: 2017) Chassis No: ZYX102003168
Colour: Black Odometer: 101466 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	43,621.59	4,260.89	39,360.70	90.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,470.00	1,990.00	9,480.00	82.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	55,091.59	6,250.89	48,840.70	88.65
Approved Total (Overridden) (\$\$)		5,000.00		
Nett Amount (\$\$)	55,091.59	5,000.00	50,091.59	90.92

INSPECTION

Date of Assignment: 21/06/2022
Date Inspected: 08/09/2021 Inspected At: C.s.ong Auto Pte Ltd (HQ)
10, ANG MO KIO IND PARK 2A #02-16 AMK
AUTO POINT SINGAPORE 568047
Singapore 568047
Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2022)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS9061Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,672.40 FL	*- FL
2	1		*BONNET LOCK	Not Necessary	321.92 FL	*- FL
3	1		*FRONT GRILLE	Not Necessary	1,029.40 FL	*- FL
4	1		*FRONT GRILLE LOGO	Not Necessary	1,496.50 FL	*- FL
5	1		*FRONT RADAR SUB ASSY	Not Necessary	3,592.51 FL	*- FL
6	2		*HEAD LAMP LH / RH	Not Necessary	7,784.08 FL	*- FL
7	2		*HEAD LAMP LOWER BRACKET LH / RH	Not Necessary	586.20 FL	*- FL
8	1		*FRONT BUMPER	Mtg Cracked	1,042.50 FL	*869.90 FL
9	2		*FRONT BUMPER SIDE RETAINER LH / RH	Not Necessary	259.78 FL	*- FL
10	2		*FRONT BUMPER SIDE GARNISH LH / RH	Not Necessary	642.04 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	498.20 FL	*- FL
12	2		*FRONT BUMPER FOG LAMP LH / RH	Not Necessary	842.04 FL	*- FL
13	1		*FRONT BUMPER SPONGE	Not Necessary	321.92 FL	*- FL
14	1		*FRONT SUPPORT PANEL	Not Necessary	1,984.50 FL	*- FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	342.51 FL	*- FL
16	1		*A/C CONDENSOR	Not Necessary	1,782.94 FL	*- FL
17	1		*A/C CONDENSOR LOW PRESSURE PIPE	Not Necessary	394.50 FL	*- FL
18	1		*A/C CONDENSOR HIGH PRESSURE PIPE	Not Necessary	892.50 FL	*- FL
19	1		*RADIATOR ASSY	Not Necessary	2,109.80 FL	*- FL
20	1		*RADIATOR FAN COMPLETE	Not Necessary	1,249.50 FL	*- FL
21	1		*BOOTLID	Bent	2,943.29 FL	*1,120.85 FL
22	1		*BOOTLID LOGO	Not Necessary	101.92 FL	*- FL
23	1		*BOOTLID CHR EMBLEM	Not Necessary	105.34 FL	*- FL
24	1		*BOOTLID HYBRID EMBLEM	Not Necessary	134.29 FL	*- FL
25	1		*BOOTLID LOCK	Not Necessary	301.90 FL	*- FL
26	1		*BOOTLID WEATHER STRIP	Necessary	378.10 FL	*240.30 FL
27	1		*BOOTLID STRIKER LOCK	Not Necessary	71.90 FL	*- FL
28	1		*BOOTLID INNER TRIM BOARD	Not Necessary	699.81 FL	*- FL
29	2		*BOOTLID LAMP LH / RH	Not Necessary	978.20 FL	*- FL
30	1		*REAR BUMPER	Distorted	1,149.82 FL	*545.10 FL
31	2		*REAR BUMPER SIDE RETAINER LH / RH	Not Necessary	190.00 FL	*- FL
32	2		*REAR BUMPER REFLECTOR LH / RH	Not Necessary	196.38 FL	*- FL
33	2		*REAR BUMPER REFLECTOR GARNISH LH / RH	Not Necessary	291.84 FL	*- FL
34	1		*REAR BUMPER SENSOR (4PCS)	2PcsDamaged/2PcsNotNecessary	1,284.04 FL	*570.00 FL
35	4		*REAR BUMPER SENSOR HOLDER	Serviceable	40.00 FL	*- FL
36	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	1,492.83 FL	*- FL
37	1		*REAR BUMPER LOWER LID	Cracked / Dented	698.29 FL	*428.71 FL
38	1		*REAR BUMPER LOWER LID LAMP	Mtg Deformed	419.80 FL	*145.40 FL
39	1		*REAR REINFORCEMENT BAR	Dented	1,014.29 FL	*420.10 FL
40	1		*REAR BUMPER SPONGE	Not Necessary	329.84 FL	*- FL
41	1		*REAR END PANEL	Dented	1,492.57 FL	*680.10 FL
42	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	392.84 FL	*189.20 FL
43	1		*SPARE WHEEL PANEL	Not Necessary	2,019.40 FL	*- FL
44	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	419.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SPARE WHEEL PANEL TOOL BOX	Not Necessary	331.92 FL	*- FL
46	1		*REAR KEYLESS SENSOR	Mtg Cracked	298.77 FL	*106.90 FL
47	1		*REAR KEYLESS BUZZER	Not Necessary	319.81 FL	*- FL
48	1		*REAR WINDSCREEN MOULDING	Necessary	349.82 FL	*211.30 FL
49	2		*REAR FENDER LH / RH	Not Necessary	4,024.80 FL	*- FL
50	2		*REAR FENDER INNER TRIM BOARD LH / RH	Not Necessary	2,182.40 FL	*- FL
51	1		*REAR EXHAUST PIPE	Not Necessary	1,892.45 FL	*- FL
52	1		*REAR EXHAUST MOUNTING	Not Necessary	94.25 FL	*- FL
53	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	210.42 FL	*- FL
54	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
55	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
56	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
57	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
58	1		*FRONT BUMPER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*COOLANT	Not Necessary	100.00 FS	*- FS
60	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
61	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
62	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
63	1		*BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
65	1		*REAR BUMPER LOWER LID CLIPS	Not Necessary	50.00 FS	*- FS
66	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
67	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
68	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
69	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
70	1		*REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
71	1		*FRONT REINFORCEMENT BAR	Not Necessary	1,092.52 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	57,818.79	5,642.86
- List Item Discount on L Items 25.00/25.00% (\$\$)	14,197.20	1,381.97
Total Parts (\$\$)	43,621.59	4,260.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	600.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	200.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,400.00	500.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,400.00	600.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSOR TO FACILITATE REPAIRS	New	200.00	0.00
8	TO RNR RADIATOR ASSY TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	200.00	0.00
10	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	120.00	40.00
11	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	400.00	120.00
12	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	150.00	60.00
13	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	0.00
14	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	150.00
Gross Labour Cost (\$\$)			11,470.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >