



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2106518

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 17/09/2021
Reference CC4/LPC21009430/Aea3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMR 644T
Insured Veh. 5025S
Claim No. 20/21/21/VC40/024928
Policy No. Z/20/VC40/109099-001
Accident Date 06/09/2021
Inspection Date 08/09/2021

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21009430/Aea3q2 Date: 17/09/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	5025S	Veh. Inspected	SMR 644T	
Policy No.	Z/20/VC40/109099-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC40/024928	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	07/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0323420	Colour	BLACK	
Odometer	107075 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	GLEDE	6 mm	
L/H Front Tyre	205/60 R16	GLEDE	6 mm	
R/H Rear Tyre	205/60 R16	GLEDE	6 mm	
L/H Rear Tyre	205/60 R16	GLEDE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2021	Inspection Date	08/09/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMR 644T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT O/S SIDE MIRROR COVER	MISSING	233.20	135.00
1	FRONT O/S SIDE MIRROR	CUT	636.40	636.40
1	FRONT O/S DOOR	TO REPAIR SEE LABOUR	1,259.20	-
1	FRONT O/S DOOR WEATHERSTRIP	NOT NECESSARY	134.60	-
1	FRONT O/S DOOR WINDOW SEAL (OUTER)	NOT NECESSARY	80.00	-
2	FRONT O/S DOOR HINGES (UPPER & LOWER)	NOT NECESSARY	220.00	-
1	FRONT O/S DOOR STRIKER	NOT NECESSARY	146.50	-
1	FRONT O/S DOOR LOCK	NOT NECESSARY	260.40	-
1	FRONT O/S DOOR LOCK (CATCH)	NOT NECESSARY	110.00	-
1	FRONT O/S DOOR WINDOW CHANNEL	NOT NECESSARY	325.40	-
1	FRONT O/S DOOR WINDOW CHANNEL BRACKET	NOT NECESSARY	87.50	-
1	FRONT O/S DOOR WINDOW MOTOR	NOT NECESSARY	564.60	-
1	REAR O/S DOOR	NOT NECESSARY	1,444.60	-
1	REAR O/S DOOR WEATHERSTRIP	NOT NECESSARY	144.60	-
	LESS 20% DISCOUNT		-1,129.40	-154.28
			4,517.60	617.12
	<u>LABOUR</u>			
	TO DISMANTLE ,STRAIGHTEN AND WELDING .INCLUSIVE OF THE REPAIR OF FRONT O/S DOOR .		500.00	200.00
	TO SPRAY PAINTING .		600.00	300.00
	TO REMOVE AND REPLACE FRONT AND REAR O/S DOOR .	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR REVERSE SENSOR .	NOT NECESSARY	60.00	-
	TO REMOVE AND REPLACE FRONT O/S SIDE MIRROR .	NOT NECESSARY	100.00	-
	TO CHECK AND RESET FAULT CODE.	NOT NECESSARY	180.00	-
	TO CHECK WIRING .	NOT NECESSARY	140.00	-
	TO RE-SEAL ANTI-RUST.	NOT NECESSARY	50.00	-
			1,780.00	500.00
	GRAND TOTAL		6,297.60	1,117.12



RECOMMENDED COST OF REPAIRS			1,117.12
-----------------------------	--	--	----------

Report Ref No. CC4/LPC21009430/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMR 644T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

