

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3AIG21009431KPS3Q2

Date:

13/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2070034138

Claimant Vehicle No : SHD9096Z**Insured Vehicle No :**

SKD905M

Date of Loss: 04/09/2021

Nature of Claim:

TP

Claim No:

4626339316SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD9096Z**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZR2B93796

Reg. Date: 19/12/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU303078690

Colour: Metallic Pearl White/Red

Odometer: 351363 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Sailun 8 mm

Rear Left Side:

Sailun 6 mm

Front Right Side: Sailun 8 mm

Rear Right Side:

Sailun 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,661.50	1,443.95	7,217.55	83.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,100.00	650.00	5,450.00	89.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,761.50	2,093.95	12,667.55	85.81
+ GST 7.00/7.00% (S\$)	1,033.31	146.58	886.73	85.81

Nett Amount (S\$)	15,794.81	2,240.53	13,554.28	85.81
+ Loss of Use (4.5 x S\$50.00/day) (S\$)		225.00		
+ Car Rental (4.5 x S\$96.30/day) (S\$)		433.35		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,906.33		
Global Sum Settlement (S\$)		2,850.00		

INSPECTION

Date of Assignment: 07/09/2021

Date Inspected: 07/09/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled / Dented	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Cut / Dented	576.30 FL	*576.30 FL
4	1		*SEAL ,REAR BUMPER SIDE ,LH	Serviceable	88.50 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	650.30 FL	*- FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
8	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
9	1		*LENS AND BODY ,REAR LAMP ,LH (LOWER)	Serviceable	502.00 FL	*- FL
10	1		*LENS & BODY ,REAR COMBINATION LAMP ,LH (UPPER)	Serviceable	443.30 FL	*- FL
11	1		*LENS AND BODY ,REAR LAMP, RH (LOWER)	Serviceable	502.00 FL	*- FL
12	1		*LENS & BODY ,REAR COMBINATION LAMP RH (UPPER)	Serviceable	451.80 FL	*- FL
13	1		*MOULDING SUB-ASSY ,ROOF DRIP SIDE FINISH ,REAR LH	Serviceable	54.40 FL	*- FL
14	1		*MOULDING SUB-ASSY ,ROOF DRIP SIDE FINISH ,REAR RH	Serviceable	54.40 FL	*- FL
15	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
16	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
17	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
18	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
19	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
20	1		*SPOILER SUB-ASSY ,REAR	Serviceable	1,575.40 FL	*- FL
21	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Repair	925.60 FL	*- FL
22	1		*ORNAMENT SUB-ASSY ,BACK DOOR	Necessary	47.90 FL	*47.90 FL
23	1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME NO.2	Necessary	54.60 FL	*54.60 FL
24	1		*PLATE ,BACK DOOR NAME NO.1	Necessary	54.60 FL	*54.60 FL
25	1		*COVER REAR FLOOR (CTR)	Cracked	229.90 FL	*229.90 FL
26	1		*COVER,FLOOR UNDER NO.2 (RH)	Serviceable	241.90 FL	*- FL
27	1		*COVER,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
28	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
29	1		*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*50.00 FS
30	1		*BOOTLID STICKER TRANS-CAB	Necessary	100.00 FS	*30.00 FS
31	1		*BOOTLID STICKER 6555-3333	Necessary	100.00 FS	*30.00 FS
32	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
33	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
34	1		*REAR BUMPER PROTECTOR	Necessary	180.00 FS	*30.00 FS
35	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*SET TAILLAMP CLIP	Not Necessary	100.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					11,042.00	1,878.60
- List Item Discount on L Items 25.00/25.00% (\$)					2,380.50	434.65
Total Parts (\$)					8,661.50	1,443.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,000.00	400.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
11	TOWING FEE	New	200.00	0.00
Gross Labour Cost (\$\$)			6,100.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >