

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21009432/KPA3Q2**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100362088
Claimant Vehicle No :	SHD5180P	Insured Vehicle No :	SCZ2626J
Date of Loss:	04/09/2021	Nature of Claim:	TP
		Claim No:	5936441528SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5180P		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZR2B90982
Reg. Date:	19/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU803078426
Colour:	Metallic Pearl White/Red	Odometer:	214881 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,236.92	1,334.30	3,902.62	74.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	650.00	4,750.00	87.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	10,636.92	1,984.30	8,652.62	81.35
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	07/09/2021	
Date Inspected:	07/09/2021	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,REAR BUMPER	Bent	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	*332.70 FL
3	1		*GUARD,REAR BUMPER,CENTER	Bent	576.30 FL	*576.30 FL
4	1		*FILLER,REAR BUMPER EXTENSION,RH	Mtg Cracked	123.70 FL	*123.70 FL
5	1		*LENS AND BODY,REAR LAMP,RH (LOWER)	Serviceable	502.00 FL	*- FL
6	1		*LENS & BODY,REAR COMBINATION LAMP,RH (UPPER)	Serviceable	451.80 FL	*- FL
7	1		*MOULDING SUB-ASSY,ROOF DRIP SIDE FINISH,REAR RH	Serviceable	54.40 FL	*- FL
8	1		*PANEL SUB-ASSY,BACK DOOR	Repair	1,147.80 FL	*- FL
9	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Repair	925.60 FL	*- FL
10	1		*ORNAMENT SUB-ASSY,BACK DOOR	Necessary	47.90 FL	*47.90 FL
11	1		*PLATE,LUGGAGE COMPARTMENT DOOR NAME.NO 2	Necessary	54.60 FL	*54.60 FL
12	1		*PLATE,BACK DOOR NAME.NO 1	Necessary	54.60 FL	*54.60 FL
13	1		*COVER,FLOOR UNDER,NO 2 (RH)	Serviceable	241.90 FL	*- FL
14	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
15	1		*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*50.00 FS
16	1		*BOOTLID STICKER TRANSCAB	Necessary	100.00 FS	*30.00 FS
17	1		*BOOTLID STICKER 65553333	Necessary	100.00 FS	*30.00 FS
18	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
19	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
20	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS
21	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
22	2		*SET TAILLAMP CLIP	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,475.90	1,742.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,238.98	408.10
Total Parts (\$\$)	5,236.92	1,334.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
2	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
3	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	1,750.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,750.00	400.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,400.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >