

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21009434/AGVF3E2

**Date:** 23/05/2022

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001831879

**Claimant Vehicle No :** SJQ3778L

**Insured Vehicle No :** GBJ8345B

Date of Loss: 06/09/2021

Nature of Claim: TP

Claim No: 262260

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJQ3778L**

Make & Model: HONDA CROSSROAD, 1.8 (A)

Engine No: R18A3011687

Reg. Date: 17/04/2009 (Man. Year: 2008)

Chassis No: RT11008620

Colour: Black

Odometer: 321554 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,479.04	3,562.72	2,916.32	45.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	1,520.00	2,240.00	59.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,239.04</b>	<b>5,082.72</b>	<b>5,156.32</b>	<b>50.36</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,050.00</b>		
<b>(S\$)</b>	10,239.04	4,050.00	6,189.04	60.45
<b>+ GST 7.00/7.00% (S\$)</b>	716.73	283.50	433.23	60.45
<b>Nett Amount (S\$)</b>	<b>10,955.77</b>	<b>4,333.50</b>	<b>6,622.27</b>	<b>60.45</b>

### INSPECTION

Date of Assignment: 08/09/2021

Date Inspected: 08/09/2021 Inspected At:

Cas Garage Pte Ltd (HQ)  
No.1, Kaki Bukit Ave 6, #02-22 Autobay  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 May 2022)
<b>Parts:</b>	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJQ3778L)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	680.00 FL	*680.00 FL
2	1		*REAR DOOR PROTECTOR RH	Cut	285.50 FL	*285.50 FL
3	1		*REAR FENDER RH	Not Necessary	1,200.00 FL	*- FL
4	1		*REAR FENDER PROTECTOR RH	Repair	166.60 FL	*- FL
5	1		*REAR FENDER INNER COWLING RH	Not Necessary	147.20 FL	*- FL
6	1		*REAR FENDER QUARTER GLASS RH	Not Necessary	580.00 FL	*- FL
7	1		*REAR TAILLAMP RH	Not Necessary	430.00 FL	*- FL
8	1		*REAR BUMPER	Torn	625.00 FL	*625.00 FL
9	1		*REAR BUMPER PROTECTOR RH	Not Necessary	136.00 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER RH	Necessary	48.00 FL	*48.00 FL
11	1		*REAR WHEEL BEARING W HUB RH	Damaged	430.00 FL	*430.00 FL
12	1		*REAR KNUCKLE ARM RH	Damaged	597.50 FL	*597.50 FL
13	1		*REAR UPPER ARM RH	Bent	245.30 FL	*245.30 FL
14	1		*REAR LOWER ARM RH	Bent	497.20 FL	*497.20 FL
15	1		*REAR SHOCK ABSORBER RH	Bent	282.40 FL	*282.40 FL
16	1		*REAR STABILIZER LINK RH	Not Necessary	135.60 FL	*- FL
17	1		*SET REAR FENDER INNER COWLING CLIPS RH	Not Necessary	30.00 FS	*- FS
18	1		*REAR FENDER QUARTER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
19	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*REAR TYRE LH	Punctured	350.00 FS	*180.00 FS
21	1		*REAR RIM RH	Cut	800.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,776.30</b>	<b>4,300.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,297.26	738.18
<b>Total Parts (\$\$)</b>	<b>6,479.04</b>	<b>3,562.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PANEL BEAT / STRAIGHTEN / REALIGN ACCIDENT AFFECTED AREAS	New	1,500.00	600.00
2	TO RESPRAY ACCIDENT AFFECTED AREAS	New	1,500.00	600.00
3	TO TUFF COAT AFFECTED AREAS	New	150.00	40.00
4	TO REMOVE / REPLACE REAR FENDER GLASS RH	New	120.00	0.00
5	TO REMOVE / REFIX RH REAR UPHOLSTERY	New	120.00	0.00
6	TO REPLACE RH REAR UNDERCARRIAGE PARTS	New	250.00	200.00
7	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,760.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >