



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 5236C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	700.00	-
1	FRONT BUMPER SIDE COVER LH	NOT NECESSARY	85.00	-
1	FRONT BUMPER BRACKET LH	NOT NECESSARY	255.00	-
1	FRONT GRILLE	NOT NECESSARY	550.00	-
1	FRONT GRILLE EMBLEM	NOT NECESSARY	75.00	-
1	FRONT HEADLAMP LH	CUT	975.00	895.00
1	FRONT CORNER PANEL LH	NOT NECESSARY	375.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,702.30	-
	LESS 25% DISCOUNT		-1,179.33	-223.75
			3,537.97	671.25
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	40.00	-
1	DECAL "COMPANY NAME & LOGO" (SN)	NECESSARY	250.00	180.00
			290.00	180.00
	<b><u>LABOUR</u></b>			
	TO CHECK FRONT WIRING AND LIGHTING SYSTEM.		60.00	30.00
	TO PANEL BEATING AND REMOVE & REFIX PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR LH.		500.00	200.00
	TO SPRAY PAINT ON AFFECTED AREAS.		600.00	400.00
	TO REMOVE & REPLACE STICKERS ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
			1,360.00	630.00
	<b>GRAND TOTAL</b>		<b>5,187.97</b>	<b>1,481.25</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>

Report Ref No. CS/AGI21009436/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.