

ASS. REC. BY: Tang JHREF: CS/ALG 21009437/T113

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 4160K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 82K Yr Regn: 2018 / Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz GLC 250 4MATIC 1991Colour: Black A/C: Insured / Std / NI / NASp. Reading: 45164 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDC 2539 462 F 479788

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim, or

Tyre Size: F: 235/55R19R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 8/9/21 @ 1pmSurvey held at TSC Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>GIA in Merimen</u>
	LUMP SUM \$14400, 7DAYS
	RED: 27556.65;65%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L&L (F) _____

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	\$ 1,493.80 <i>de ✓</i>
2	2	Rear bumper bracket	\$ <i>RHX</i> 222.30 <i>LH-ver ✓</i>
3	2	Rear bumper reflector	\$ <i>RHX</i> 186.40 <i>LH-ver ✓</i>
4	1	Rear bumper tow cover	\$ 98.10 <i>de ✓</i>
5	2	Rear bumper retainer	\$ 387.90 <i>LH-de ✓ RHX</i>
6	1	Rear bumper reinforcement	\$ 809.60 <i>bt ✓</i>
7	1	Rear bumper centre chrome moulding	\$ 295.10 <i>cuq ✓</i>
8	1	Rear bumper inner beam <i>plastic bracket</i>	\$ 495.50 <i>de ✓</i>
9	1	Rear tailgate assy	\$ 3,549.60 <i>bt ✓</i>
10	1	Rear tailgate weatherstrip	\$ 188.10 <i>fin ✓</i>
11	1	Rear tailgate inner board	\$ 526.40 <i>cuq ✓</i>
12	1	Rear tailgate centre logo	\$ 174.90 <i>neg ✓</i>
13	1	Rear tailgate 'GLC 250' emblem	\$ 133.40 <i>re ✓</i>
14	1	Rear tailgate '4matic' emblem	\$ 133.40 <i>re ✓</i>
15	1	Rear tailgate lock mechanism	\$ 380.50 <i>bt ✓</i>
16	1	Rear tailgate lock catch	\$ 85.60 <i>x</i>
17	2	Rear tailgate number plate lamp	\$ 188.10 <i>x</i>
18	1	Rear tailgate auto switch	\$ 281.50 <i>x</i>
19	2	Rear tailgate inner handle	\$ 363.80 <i>x</i>
20	1	Rear tailgate inner lamp	\$ 88.80 <i>x</i>
21	2	Rear tailgate dampers	\$ 592.90 <i>x</i>
22	2	Rear tailgate hinges	\$ 266.70 <i>x</i>
23	2	Rear tailgate rubber stopper	\$ 82.90 <i>re ✓</i>
24	1	Rear left tailgate taillamp	\$ 762.40 <i>cuq ✓</i>
25	1	Rear right tailgate taillamp	\$ 762.40 <i>cuq ✓</i>
26	1	Rear left taillamp	\$ 812.20 <i>cuq ✓</i>
27	1	Rear right taillamp	\$ 812.20 <i>cuq ✓</i>
28	1	Rear left taillamp bracket	\$ 261.20 <i>de ✓</i>
29	1	Rear right taillamp bracket	\$ 261.20 <i>de ✓</i>
30	1	Rear end lower panel	\$ 1,545.10 <i>bt ✓</i>
31	1	Rear end lower panel top garnish	\$ 172.50 <i>de ✓</i>
32	1	Rear exhaust muffler complete assy	\$ 3,678.90 <i>bt ✓</i>
33	2	Rear exhaust muffler rubber mounting	\$ 88.90 <i>de ✓</i>
34	1	Rear left exhaust end cover	\$ 450.10 <i>bt ✓</i>
35	1	Rear right exhaust end cover	\$ 450.10 <i>x</i>
36	2	Rear exhaust heat shield	\$ 603.40 <i>bt ✓</i>
37	1	Rear windscreen glass moulding	\$ 288.80 <i>neg ✓</i>
38	1	Rear windscreen glass centre garnish	\$ 168.90 <i>neg ✓</i>
39	2	Rear windscreen glass side inner garnish	\$ 265.30 <i>neg ✓</i>
40	1	Rear floor panel	\$ 1,825.20 <i>xRX</i>
41	1	Rear floor panel carpet	\$ 382.50 <i>x</i>
42	1	Rear top board	\$ 398.50 <i>x</i>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Qty	Parts Description	Estimated Parts Price
43	1	Rear left fender	\$ 2,807.80 X
44	1	Rear right fender	\$ 2,807.80 X
45	1	Rear left fender side protector	\$ 298.20 <i>del</i>
46	1	Rear right fender side protector	\$ 298.20 X
47	1	Rear left quarter glass moulding	\$ 280.30 X
48	1	Rear right quarter glass moulding	\$ 280.30 X
49	1	Rear left air duct ventilator	\$ 80.30 X
50	1	Rear right air duct ventilator	\$ 80.30 X
51	1	Front left passenger headrest restraint	\$ 985.10 X
52	1	Front right driver headrest restraint	\$ 985.10 X
less 10%			\$ 33,918.50
			\$ 3,391.85
			\$ 30,526.65
<u>Special Nett Items</u>			
1	10	Rear bumper clips	\$ 60.00 <i>30 net</i>
2	6	Rear end lower panel top garnish clips	\$ 40.00 <i>2 one</i>
3	1	Rear end lower panel sealant	\$ 120.00 <i>5 one</i>
4	4	Rear bumper reverse sensor	\$ 1,600.00 <i>nm / 600</i>
5	4	Rear bumper centre chrome moulding clips	\$ 40.00 <i>2 one</i>
6	1	Rear no plate with garnish	\$ 100.00 X
7	1	Rear bumper lower spoiler	\$ 1,600.00 <i>del / 600</i>
8	1	Rear bumper lower spoiler sealant	\$ 100.00 <i>2 one X an</i>
9	12	Rear bumper lower spoiler clips	\$ 80.00 <i>2 one</i>
10	1	Rear floor panel insulator pad	\$ 180.00 X
11	1	Rear floor panel sealant	\$ 180.00 X
12	1	Rear view camera	\$ 450.00 X
13	8	Rear tailgate inner board clips	\$ 50.00 <i>2 one</i>
14	1	Rear windscreen glass sealant	\$ 100.00 <i>6 one</i>
15	1	Rear left fender sealant	\$ 100.00 X
16	1	Rear right fender sealant	\$ 100.00 X
17	8	Rear windscreen glass centre garnish clips	\$ 50.00 X
18	2 set	Rear windscreen glass side inner garnish clips	\$ 80.00 X
19	1	Rear left quarter glass sealant	\$ 80.00 X
20	1	Rear right quarter glass sealant	\$ 80.00 X
21	6	Rear left fender side protector clips	\$ 40.00 <i>1 one</i>
22	6	Rear right fender side protector clips	\$ 40.00 X
			\$ 5,270.00
Total parts			\$ 35,796.65

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJP82K Mercedes Benz GLC250

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,600.00 <i>9000</i>
2	To putty and spray painting rear portion.	\$ 1,600.00 <i>900</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>30</i>
4	To remove and install rear tailgate lock mechanism.	\$ 80.00 <i>60</i>
5	To remove and install rear exhaust muffler assy.	\$ 120.00 <i>80</i>
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 140.00 <i>60</i>
7	To apply anti rust proofing to rear affected area.	\$ 140.00 <i>40</i>
8	To remove and install rear bumper reverse sensor.	\$ 80.00 <i>30</i>
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 <i>120</i>
10	To remove and install rear view camera.	\$ 80.00 <i>X</i>
11	To remove and install rear fuel tank to facilitate the repair.	\$ 250.00 <i>X</i>
12	To use diagnostic equipment to scan and calibrate rear electrical system.	\$ 350.00 <i>200</i>
13	To use diagnostic equipment to scan for fault code, erased and reset if necessary.	\$ 350.00 <i>200</i>
14	To remove and install rear left quarter glass.	\$ 80.00 <i>X</i>
15	To remove and install rear right quarter glass.	\$ 80.00 <i>X</i>
16	Towing service.	\$ 120.00 <i>80 towing receipt</i>
17	To remove and install front left passenger headrest restraint system.	\$ 300.00 <i>X</i>
18	To remove and install front right driver headrest restraint system.	\$ 300.00 <i>X</i>
19	To reset front air bag lamp.	\$ 300.00 <i>X</i>
Total labour :		\$ 6,160.00

Total parts : \$ 35,796.65

Total labour : \$ 6,160.00

Total repair cost : \$ 41,956.65

Tanpin 92495749
WP' 8/19/21 24pm
** To check part prices*
c/s reply after repair
Tanpin @ Kuantan
0.7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: