

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21009439/AVCN2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant:	CHIANG FOCK PONG	Policy No:	1700086735	
Date of Loss:	02/09/2021	Nature of Claim:	OD	Claim No: 4970743135SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU5988P		
Make & Model:	AUDI Q2, 999cc 1.0 TFSI S TRONIC (A)	Engine No:	CHZ594541
Reg. Date:	07/12/2017 (Man. Year: 2017)	Chassis No:	WAUZZZGA6JA040009
Colour:	White	Odometer:	74901 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$86,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,738.00	6,724.00	5,014.00	42.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,752.00	1,492.00	4,260.00	74.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,490.00	8,216.00	9,274.00	53.02
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	16,690.00	7,416.00	9,274.00	55.57
+ GST 7.00/7.00% (S\$)	1,168.30	519.12	649.18	55.57
Nett Amount (S\$)	17,858.30	7,935.12	9,923.18	55.57

INSPECTION

Date of Assignment:	08/09/2021		
Date Inspected:	07/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,042.00 FS	*714.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	347.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE	Not Necessary	197.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Cut	169.00 FS	*135.20 FS
5	1		*FRONT BUMPER AIR GUIDE CAP-RH	Not Necessary	59.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	299.00 FS	*238.80 FS
7	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	156.00 FS	*- FS
8	1		*FRONT WHEEL SPOILER-RH	Not Necessary	34.00 FS	*- FS
9	1		*FRONT BUMPER AIR GUIDE ADAPTER-RH	Not Necessary	42.00 FS	*- FS
10	1		*RADIATOR GRILLE	Cracked	1,411.00 FS	*1,128.80 FS
11	1		*RADIATOR STRIKER PLATE	Not Necessary	124.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION-RH	Not Necessary	36.00 FS	*- FS
13	1		*CARRIER FOAM FILLER PIECE	Not Necessary	78.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Not Necessary	723.00 FS	*- FS
15	1		*RADIATOR DISTANCE PIECE	Not Necessary	14.00 FS	*- FS
16	1		*FRONT BUMPER TOP COVER	Not Necessary	100.00 FS	*- FS
17	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
18	1		*AIR-CONDITIONER STICKER	Not Necessary	8.00 FS	*- FS
19	1		*HORN-RH	Not Necessary	180.00 FS	*- FS
20	1		*HORN BRACKET-RH	Not Necessary	31.00 FS	*- FS
21	1		*FRONT HEADLIGHT MOUNTING	Not Necessary	118.00 FS	*- FS
22	1		*FRONT HEADLIGHT-RH	Cut	4,915.00 FS	*3,932.00 FS
23	1		*FRONT HEADLIGHT CYLINDER WASHER-RH	Not Necessary	142.00 FS	*- FS
24	1		*FRONT HEADLIGHT WASHER HOSE	Not Necessary	182.00 FS	*- FS
25	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	644.00 FS	*514.40 FS
26	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	196.00 FS	*- FS
27	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PART	Not Necessary	57.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE-RH	Not Necessary	31.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE SEAL-RH	Not Necessary	7.00 FS	*- FS
30	1		*RADIATOR AIR GUIDE-UPPER CENTER	Not Necessary	22.00 FS	*- FS
31	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
32	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 11,738.00 6,724.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	0.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT.TO REPAIR RHS FRONT FENDER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,800.00	500.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,752.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >