

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009440/KVCN2**Date:** 03/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00075752100
Claimant Vehicle No :	SJS188Z	Insured Vehicle No :	SJL4171G
Date of Loss:	06/09/2021	Nature of Claim:	TP
		Claim No:	SNM21D205052/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS188Z	Engine No:	2AR1398834
Make & Model:	LEXUS ES300H, 2.5 (A)	Chassis No:	JTHBW1GG102110848
Reg. Date:	31/12/2015 (Man. Year: 2015)	Odometer:	111859 km
Colour:	Metallic Pearl White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,589.60	1,881.75	707.85	27.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,520.00	960.00	560.00	36.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,109.60	2,841.75	1,267.85	30.85
+ GST 7.00/7.00% (\$\$)	287.67	198.92	88.75	30.85
Nett Amount (\$\$)	4,397.27	3,040.67	1,356.60	30.85

INSPECTION

Date of Assignment:	08/09/2021	
Date Inspected:	10/09/2021 Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2021)
Parts:	143	LEXUS ES300H 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS188Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILAMP LH	Cut	727.20 FL	*727.20 FL
2	1		*TAILAMP LOWER BEAM LH	Serviceable	125.40 FL	*- FL
3	1		*REAR BUMPER	Bent	1,015.00 FL	*1,015.00 FL
4	1		*REAR BUMPER SIDE RETAINER LH	Distorted	100.00 FL	*100.00 FL
5	15		*REAR BUMPER CLIPS	Necessary	67.50 FL	*67.50 FL
6	1		*REAR BUMPER REVERSE SENSOR OUTER LH	Cracked	490.80 FL	*477.10 FL
7	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	57.20 FL	*57.20 FL
8	1		*REAR BUMPER REFLECTOR LH	Cracked	75.60 FL	*65.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Repair	654.60 FL	*- FL
10	1		*REAR BUMPER SPONGE	Serviceable	139.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,452.80	2,509.00
- List Item Discount on L Items 25.00/25.00% (S\$)	863.20	627.25
Total Parts (S\$)	2,589.60	1,881.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRINGS,WIRE SPCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	20.00
2	TO REMOVE AND REINSTALL CUSHIONS,SEATS,BACKREST,INNER TRIM,GARNISH,ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	New	120.00	0.00
3	TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS	New	80.00	60.00
4	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS,TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME	New	500.00	400.00
7	TO SPRAY REAR FENDER LH,REAR BUMPER	New	600.00	480.00
Gross Labour Cost (\$\$)			1,520.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >