2/11/22, 11:44 AM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI21009442/VTCN2

11/02/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMHCSNA00009012101

**Claimant Vehicle** No:

SMX8224M

Insured Vehicle No:

SLH5787X

Date of Loss:

Reg. Date:

04/09/2021

Nature of Claim: TP

No:

SNM21D205027/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMX8224M Reg No:

TOYOTA COROLLA ALTIS, 1.6 (A) Make & Model:

29/10/2014 (Man. Year: 2014)

Engine No: Chassis No: Odometer:

MR053REH104518663

Yes

1ZRY111507

73839 km

Colour: Red 1598 cc

**Engine Capacity:** N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Front Left Side: Rear Left Side: Continental 5 mm Continental 5 mm Front Right Side: Rear Right Side: Continental 5 mm Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,915.00	2,095.00	820.00	28.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,184.45	1,142.45	42.00	3.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,099.45	3,237.45	862.00	21.03
+ GST 7.00/7.00% (S\$)	286.96	226.62	60.34	21.03
Nett Amount (S\$)	4.386.41	3,464.07	922.34	21.03

**INSPECTION** 

Date of Assignment: 08/09/2021 Present Location: Jin Auto Services Pte Ltd (Defu)

Jin Auto Services Pte Ltd (Defu)

Date Inspected: 08/09/2021 Blk 14 Defu Lane 10, #01-410/412 Inspected At:

Singapore 539195

Estimated Period of Repair: 4.0 days

DENISE TAY KWEE CHENG Adjuster: Thevan Thomas Karthikesavan Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

### Reference

2/11/22, 11:44 AM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Feb 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMX8224M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No. Qty Part No.	Particulars Con	dition	Repairer's	Amount
1 1	*TOTAL PART		2,860.00 F	*2,040.00 F
Supplementary #1	*DOOT! ID DUDDED		55.00 F	*55.00.5
F=Franchise part.	*BOOTLID RUBBER		55.00 F	*55.00 F
i –i ranonise part.		Total Parts (S\$)	2,915.00	2,095.00
	Report was unsubmitted dur	ng this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			***************************************
1	TOTAL LABOUR	New	394.80	352.80
2	TOTAL PAINT	New	789.65	789.65
		Gross Labour Cost (S\$)	1,184.45	1,142.45
		Report was unsubmitted during this print-out.		

< END OF ESTIMATES >