

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21009447/AUCE2

**Date:** 03/11/2021

### REFERENCE

Insured/Claimant:	CHIOU YEW SENG RICHARD	Policy No:	2070149534	
Date of Loss:	02/09/2021	Nature of Claim:	OD	Claim No: 8145635350SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV9101M		
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Engine No:	DEM025618
Reg. Date:	27/10/2020 (Man. Year: 2020)	Chassis No:	WAUZZZF50MA003532
Colour:	Blue	Odometer:	13001 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$175,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,601.00	10,736.88	7,864.12	42.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,122.00	3,022.00	2,100.00	41.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,723.00</b>	<b>13,758.88</b>	<b>9,964.12</b>	<b>42.00</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>22,923.00</b>	<b>12,958.88</b>	<b>9,964.12</b>	<b>43.47</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,604.61</b>	<b>907.12</b>	<b>697.49</b>	<b>43.47</b>
<b>Nett Amount (S\$)</b>	<b>24,527.61</b>	<b>13,866.00</b>	<b>10,661.61</b>	<b>43.47</b>

### INSPECTION

Date of Assignment:	08/09/2021		
Date Inspected:	07/09/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

**Adjuster:** ADRIAN LING

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,342.00 FS	*1,873.60 FS
2	1		*FRONT BUMPER SECURING STRIP	Not Necessary	72.00 FS	*- FS
3	1		*FRONT BUMPER LOWER GRILLE - CENTER	Not Necessary	196.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	262.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	262.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	135.00 FS	*- FS
8	1		*FRONT BUMPER TRIM - RH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	114.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,694.00 FS	*- FS
11	1		*FOAM FILLER PIECE	Not Necessary	146.00 FS	*- FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	845.00 FS	*- FS
13	1		*FRONT BUMPER TOP COVER	Not Necessary	127.00 FS	*- FS
14	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
15	1		*A/C STICKER	Not Necessary	8.00 FS	*- FS
16	1		*LOCK CARRIER BRACKET	Not Necessary	137.00 FS	*- FS
17	2		*LOCK CARRIER BRACKET SUPPORT - LH / RH	Not Necessary	58.00 FS	*- FS
18	1		*BONNET	Dented	3,312.00 FS	*2,649.60 FS
19	1		*BONNET ATTACHMENT PARTS	Not Necessary	123.00 FS	*- FS
20	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	28.00 FS	*21.84 FS
21	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	58.00 FS	*43.84 FS
22	1		*BONNET STRIKER - RH	Not Necessary	214.00 FS	*- FS
23	1		*LED HEADLIGHT - RH	Cracked	7,685.00 FS	*6,148.00 FS
24	1		*HEADLIGHT BREATHER HOSE - RH	Not Necessary	36.00 FS	*- FS
25	1		*LIFT CYLINDER - RH	Not Necessary	198.00 FS	*- FS
26	1		*LIFT CYLINDER HOSE (NPA)	Not Necessary	0.00 FS	*- FS
27	1		*RADIATOR AIR GUIDE - RH	Not Necessary	32.00 FS	*- FS
28	1		*RADIATOR AIR GUIDE - RH	Not Necessary	16.00 FS	*- FS
29	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	16.00 FS	*- FS
30	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS
31	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 18,601.00 10,736.88

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,122.00</b>	<b>3,022.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >