

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009448/KQCN2**Date:** 20/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00071442001

**Claimant Vehicle No :** GBG5177E **Insured Vehicle No :** GBG5672S

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: SNM21D205056/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBG5177E**

Make & Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M) Engine No: 1KD2742203

Reg. Date: 28/08/2017 (Man. Year: 2017) Chassis No: JTFAT35Y00K208869

Colour: Silver Odometer: 62223 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195/75R15 Rear Tyre Size: 155R12X8(D)

Front Left Side: Kenda 8 mm Rear Left Side: Dunlop 3/3 mm

Front Right Side: Kenda 8 mm Rear Right Side: Dunlop 3/3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,035.00	635.25	399.75	38.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	60.00	140.00	70.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>1,235.00</b>	<b>695.25</b>	<b>539.75</b>	<b>43.70</b>

**INSPECTION**

Date of Assignment: 05/10/2021

Date Inspected: 01/10/2021 Inspected At: SERVE YOU MOTOR PTE LTD (HQ)  
BLK 5033 ANG MO KIO INDUSTRIAL PARK 2,  
#01-265  
Singapore 569536

Estimated Period of Repair: 1.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 20 Oct 2021)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBG5177E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH SIDE MIRROR	Cracked	780.00 FL	*455.30 FL
2	1		*ROUND MIRROR	Missing	220.00 FL	*160.00 FL
3	1		*BRACKET LH	Distorted	380.00 FL	*231.70 FL
						F=Franchise part. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>1,380.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>345.00</b>
					<b>Total Parts (\$\$)</b>	<b>1,035.00</b>
						<b>635.25</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE/RENEW/REFIT/STRAIGHTEN/ORIENTATE/ALIGN/REPLACEMENT/REPAIR THE ACCIDENT DAMAGED PORTION/REPLACEMENT PART	New	150.00	60.00
2	TO CHECK WIRING	New	50.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>200.00</b>	<b>60.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >