

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009451/EVCN2**Date:** 08/10/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00059322100	
Claimant Vehicle No :	SKP2530J	Insured Vehicle No :	SJL731S	
Date of Loss:	05/09/2021	Nature of Claim:	TP	Claim No: SNM21D205053/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP2530J		Engine No:	1ZRX423279
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 L CVT (A)		Chassis No:	MR053REH104510561
Reg. Date:	27/08/2014 (Man. Year: 2014)		Odometer:	73961 km
Colour:	Silver			
Engine Capacity:	1598 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,604.10	9,371.80	12,232.30	56.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,264.80	10,564.80	6,700.00	38.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,868.90	19,936.60	18,932.30	48.71
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	38,868.90	14,000.00	24,868.90	63.98
+ GST 7.00/7.00% (S\$)	2,720.82	980.00	1,740.82	63.98
Nett Amount (S\$)	41,589.72	14,980.00	26,609.72	63.98

INSPECTION

Date of Assignment:	08/09/2021	
Date Inspected:	08/09/2021	Inspected At: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	13.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Oct 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP2530J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER,FR BUMPER	Crushed	536.20 FS	*536.20 FS
2	1		*1D4 SILVER METALLIC REVERSE SE	Shorted	155.20 FS	*155.20 FS
3	1		*SUPPORT,FR BUMPER RH	Not Necessary	86.10 FS	*- FS
4	1		*SUPPORT,FR BUMPER LH	Not Necessary	86.10 FS	*- FS
5	1		*GRILLE,RADIATOR LWR	Not Necessary	171.70 FS	*- FS
6	1		*ABSORBER,FR BUMPER	Not Necessary	90.80 FS	*- FS
7	1		*REINFORCEMENT,FR	Not Necessary	403.70 FS	*- FS
8	2		*CLIP	Necessary	5.20 FS	*5.20 FS
9	2		*RETAINER,FR FENDER	Not Necessary	17.40 FS	*- FS
10	1		*GRILLE,RADIATOR	Cut	648.30 FS	*648.30 FS
11	1		*COVER,RADIATOR RH	Not Necessary	81.30 FS	*- FS
12	1		*HOOD SUB-ASSY	Dented	1,259.40 FS	*1,259.40 FS
13	1		*SEAL,HOOD	Not Necessary	32.30 FS	*- FS
14	6		*CLIP	Necessary	17.40 FS	*17.40 FS
15	1		*LOCK ASSY,HOOD	Not Necessary	136.20 FS	*- FS
16	1		*HINGE ASSY,HOOD RH	Not Necessary	59.40 FS	*- FS
17	1		*HINGE ASSY,HOOD LH	Not Necessary	59.40 FS	*- FS
18	1		*SUPPORT SUB-ASSY,HO	Not Necessary	151.10 FS	*- FS
19	1		*SUPPORT SUB-ASSY	Not Necessary	1,149.50 FS	*- FS
20	1		*RADIATOR GRILLE EMBLEM	Necessary	48.40 FS	*48.40 FS
21	1		*PLATE,LUGGAGE COMPT	Not Necessary	35.90 FS	*- FS
22	1		*PLATE,LUGGAGE COMPT	Not Necessary	35.90 FS	*- FS
23	1		*A/C CONDENSER ASSY	Not Necessary	1,820.20 FS	*- FS
24	1		*RADIATOR ASSY	Not Necessary	2,169.60 FS	*- FS
25	1		*HEADLAMP ASSY,RH	Broken	3,028.80 FS	*3,028.80 FS
26	1		*HEADLAMP ASSY,LH	Not Necessary	3,028.80 FS	*- FS
27	1		*COVER,RR BUMPER	Dented	561.50 FS	*561.50 FS
28	10		*PIECE,RR BUMPER	Necessary	41.00 FS	*41.00 FS
29	1		*RETAINER,RR BUMPER R	Not Necessary	110.50 FS	*- FS
30	1		*RETAINER,RR BUMPER R	Not Necessary	61.00 FS	*- FS
31	1		*RETAINER,RR BUMPER L	Not Necessary	110.50 FS	*- FS
32	1		*RETAINER,RR BUMPER L	Not Necessary	61.00 FS	*- FS
33	1		*REINFORCEMENT,RR	Dented	403.70 FS	*403.70 FS
34	1		*ARM RR BUMPER RH	Not Necessary	68.70 FS	*- FS
35	1		*ARM RR BUMPER LH	Not Necessary	68.70 FS	*- FS
36	1		*PANEL LAMP LOWER	Dented	676.60 FS	*676.60 FS
37	1		*PANEL SUB-ASSY,LUGG	Dented	798.90 FS	*798.90 FS
38	1		*WEATHERSTRIP LUGGAGE	Torn	177.60 FS	*177.60 FS
39	1		*ARM,LUGGAGE	Not Necessary	70.50 FS	*- FS
40	1		*ARM,LUGGAGE	Not Necessary	70.50 FS	*- FS
41	1		*LOCK ASSY LUGGAGE	Not Necessary	403.70 FS	*- FS
42	1		*PLATE,RR FLOOR	Not Necessary	244.30 FS	*- FS
43	2		*CLIP	Necessary	5.80 FS	*5.80 FS
44	1		*COVER ASSY,SPARE	Not Necessary	269.30 FS	*- FS
45	1		*LAMP ASSY,RR COMB RH	Cut	383.60 FS	*383.60 FS
46	1		*LAMP ASSY,RR COMBIN	Cut	383.60 FS	*383.60 FS

Report was unsubmitted during this print-out.

10/8/21, 10:27 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LAMP ASSY,RR LH	Not Necessary	356.60 FS	*- FS
48	1		*REFLECTOR ASSY,REFL	Not Necessary	60.40 FS	*- FS
49	1		*REFLECTOR ASSY,REFL	Not Necessary	60.40 FS	*- FS
50	1		*ELECTRICAL ANTENNA	Not Necessary	194.20 FS	*- FS
51	1		*LUGGAGE COMP EMBLEM	Necessary	62.20 FS	*62.20 FS
52	1		*PLATE,LUGGAGE COMPT	Necessary	41.40 FS	*41.40 FS
53	1		*PLATE,LUGGAGE COMPT	Necessary	46.00 FS	*46.00 FS
54	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
55	1		*R/REAR BOOT LAMP	Not Necessary	356.60 FS	*- FS
56	10		*PIECE,RR BUMPER	Necessary	41.00 FS	*41.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	21,604.10
						9,371.80
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE AND REFOCUS HEADLAMP-FRONT	New	122.40	122.40
2	SUPPLY SEALANT-FRONT	New	300.00	100.00
3	R/I AC CONDENSOR,PIPING AND REGAS-FRONT	New	360.00	0.00
4	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
5	SUPPLY REGN PLATE (PO)-FRT & BACK	New	160.00	80.00
6	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS-FRONT	New	3,600.00	1,800.00
7	RESPRAY ACC AFFECTED AREAS-FRONT	New	3,540.00	1,770.00
8	SUPPLY SEALANT-REAR	New	300.00	200.00
9	DRILL HOLE AND INSTALL REVERSE SENSOR-REAR	New	180.00	180.00
10	CHECK WIRING AND CONDUCT WATER TEST-REAR	New	122.40	122.40
11	REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID	New	540.00	540.00
12	R/I REAR REVERSE CAMERA TO FAC REPAIR-REAR	New	720.00	360.00
13	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS-REAR	New	3,600.00	2,160.00
14	RESPRAY ACC AFFECTED AREAS-REAR	New	3,540.00	2,950.00
Gross Labour Cost (\$\$)			17,264.80	10,564.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >