

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21009455/REA3Q2
Date: 15/06/2022REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SLK9943U	Insured Vehicle No :	SLS9774Z
Date of Loss:	05/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK9943U	Engine No:	1ZRY325422
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104556150
Reg. Date:	09/02/2017 (Man. Year: 2016)	Odometer:	71404 km
Colour:	Red		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,028.45	4,958.87	8,069.58	61.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	1,770.00	1,690.00	48.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,488.45	6,728.87	9,759.58	59.19
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	16,488.45	5,400.00	11,088.45	67.25
+ GST 7.00/7.00% (S\$)	1,154.19	378.00	776.19	67.25
Nett Amount (S\$)	17,642.64	5,778.00	11,864.64	67.25
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,962.45		
Global Sum Settlement (S\$)		6,960.00		

INSPECTION

Date of Assignment:	08/09/2021		
Date Inspected:	08/09/2021	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 May 2022)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLK9943U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Cracked	385.90 FL	*385.90 FL
2	1		*FRONT GRILLE LOGO	Necessary	75.30 FL	*75.30 FL
3	1		*HEADLAMP RH	Cracked	1,866.50 FL	*1,866.50 FL
4	1		*HEADLAMP LH	Not Necessary	1,866.50 FL	*- FL
5	1		*FRONT BUMPER	Repair	738.10 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	155.30 FL	*- FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	332.90 FL	*- FL
8	1		*FRONT SUPPORT PANEL UPPER (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*HEADLAMP PANEL RH (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*FRONT SUPPORT BRACE PANEL	Not Necessary	115.30 FL	*- FL
11	1		*AIR CON CONDENSER	Not Necessary	1,235.90 FL	*- FL
12	1		*REAR FENDER RH (NPA)	Not Necessary	0.00 FL	*- FL
13	1		*REAR FENDER LH (NPA)	Not Necessary	0.00 FL	*- FL
14	1		*REAR BOOT LID	Bent	1,165.30 FL	*756.00 FL
15	1		*REAR BOOT LID LOGO	Necessary	75.30 FL	*75.30 FL
16	1		*REAR BOOT LID CHROME	Cracked	388.90 FL	*280.00 FL
17	1		*REAR BOOT LID REVERSE LAMP RH	Not Necessary	625.30 FL	*- FL
18	1		*REAR BOOT LID REVERSE LAMP LH	Cracked	625.30 FL	*342.00 FL
19	1		*REAR BOOT LID HINGE RH	Not Necessary	189.50 FL	*- FL
20	1		*REAR BOOT LID HINGE LH	Not Necessary	189.50 FL	*- FL
21	1		*REAR BOOT LID LOCK	Not Necessary	285.10 FL	*- FL
22	1		*REAR TAIL LAMP RH	Not Necessary	838.50 FL	*- FL
23	1		*REAR TAIL LAMP LH	Scratched	838.50 FL	*480.00 FL
24	1		*REAR TAIL LAMP PANEL RH	Not Necessary	269.10 FL	*- FL
25	1		*REAR TAIL LAMP PANEL LH	Not Necessary	269.10 FL	*- FL
26	1		*REAR BUMPER	Deformed	685.90 FL	*545.00 FL
27	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	53.10 FL	*- FL
28	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	53.10 FL	*- FL
29	1		*REAR BUMPER REINFORCEMENT	Bent	421.30 FL	*395.00 FL
30	1		*REAR BOOT LID WEATHERSTRIP	Necessary	195.60 FL	*195.60 FL
31	1		*REAR END PANEL	Bent	1,032.50 FL	*695.00 FL
32	1		*REAR END PANEL GARNISH	Deformed	266.90 FL	*266.90 FL
33	1		*REAR FENDER INNER TRIM LH	Not Necessary	585.10 FL	*- FL
34	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
35	1		*FRONT NUMBER PLATE & HOLDER	Scratched	60.00 FS	*50.00 FS
36	1		*AIR CON GAS	Not Necessary	100.00 FS	*- FS
37	1		*REAR NUMBER PLATE & HOLDER	Scratched	60.00 FS	*50.00 FS
38	1		*REAR REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
39	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*SET REAR BUMPER REVERSE SENSORS	Not Necessary	250.00 FS	*- FS
41	2		*REAR TAIL LAMP PANEL SEALANT RH & LH	Not Necessary	100.00 FS	*- FS
42	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
43	1		*SUNDRIES (SAND PAPER ,WELDING WIRE ETC)	Necessary	60.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,984.60 6,548.50
- List Item Discount on L Items 25.00/25.00% (\$\$) 3,956.15 1,589.63

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (S\$)	13,028.45	4,958.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	New	1,200.00	700.00
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	New	100.00	0.00
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	New	150.00	80.00
4	TO REMOVE & REFIT AIR CON CONDENSER & RADIATOR	New	120.00	0.00
5	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS & CAMERA	New	100.00	60.00
6	TO REMOVE & REFIT UPHOLSTERY GARNISH AND ATTACHMENT PARTS	New	120.00	60.00
7	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	New	1,500.00	800.00
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	40.00
9	TO VACUUM ,WAXING & CLEAN	New	60.00	0.00
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	New	50.00	30.00
			Gross Labour Cost (\$\$)	3,460.00
				1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >