

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21009458/Gqce2	
	8 SHENTON WAY SINGAPORE 0688		Date:	10/09/2021		
	ATTN: ANG YVON	NE		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 7061S	Veh. Inspected	l	FBJ 3326P	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S1M03GP4	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		08/09/2021	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA TMAX 530	c.c		530	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	JYASJ091000018587	Colour		BLUE	
	Odometer	37581 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/70 R15	METZELER		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	160/60 R15	METZELER		5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			NT		
5.	. General Information					
	Accident Date	27/08/2021	Inspect Date /	Time	08/09/2021 (02:00 PM)	
	Survey held at HE XIN MOTOR					
	25 KAKI BUKIT ROAD 4 #01-75 SYNERGY @ KB SINGAPORE 417800					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
		D (N 000				

Report Ref No. CS3/ASM21009458/Gqce2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor