

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009460/ETCE2

Date: 24/09/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:
Claimant Vehicle No: SLL7672J Insured Vehicle No: XD7827E
Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: SNM21D204881/C02/XD7827E/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL7672J
Make & Model: MAZDA 3, 1.5 4 DOOR SEDAN SP (A) Engine No: P520432409
Reg. Date: 09/03/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0145058
Colour: Grey Odometer: 62232 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: West Lake 4 mm Rear Left Side: West Lake 4 mm
Front Right Side: West Lake 4 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,095.50	3,676.80	4,418.70	54.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	2,090.00	610.00	22.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,795.50	5,766.80	5,028.70	46.58
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	10,795.50	4,600.00	6,195.50	57.39
+ GST 7.00/7.00% (S\$)	755.69	322.00	433.69	57.39
Nett Amount (S\$)	11,551.19	4,922.00	6,629.19	57.39

INSPECTION

Date of Assignment: 08/09/2021
Date Inspected: 08/09/2021 Inspected At: Hin Lung Workshop (HQ)
Singapore 159722
Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2021)
Parts:	143	MAZDA 3 1.5 4 DOOR SEDAN SP (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL7672J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Dented	350.00 F	*350.00 FL
2	1		*FRONT SPLASH SHIELD RH	Not Necessary	101.00 F	*- FL
3	1		*FRONT PILLAR OUT RH	Not Necessary	762.00 F	*- FL
4	1		*PANEL SIDE SILL RH	Not Necessary	924.00 F	*- FL
5	1		*REAR PANEL FENDER RH	Dented	1,233.00 F	*1,233.00 FL
6	1		*FRONT DOOR RH	Dented	1,200.00 F	*1,062.00 FL
7	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	111.00 F	*- FL
8	1		*FRONT DOOR HINGE UPPER RH	Bent	52.00 F	*52.00 FL
9	1		*FRONT DOOR HINGE LOWER RH	Bent	53.00 F	*53.00 FL
10	1		*REAR DOOR RH	Dented	1,048.00 F	*1,048.00 FL
11	1		*REAR DOOR WHEATHERSTRIP RH	Not Necessary	111.00 F	*- FL
12	1		*REAR DOOR HINGE A RH	Bent	52.00 F	*52.00 FL
13	1		*REAR DOOR HINGE B RH	Bent	54.00 F	*54.00 FL
14	1		*FRONT MOULD BELTLINE RH	Not Necessary	86.00 F	*- FL
15	1		*FRONT MOULD SASH RH	Not Necessary	98.00 F	*- FL
16	1		*FRONT DOOR GARNISH RH	Not Necessary	52.00 F	*- FL
17	1		*REAR MOULD BELTLINE RH	Bent	76.00 F	*76.00 FL
18	1		*REAR MOULD SASH RH	Not Necessary	89.00 F	*- FL
19	1		*REAR DOOR GARNISH RH	Not Necessary	65.00 F	*- FL
20	1		*REAR DOOR GARNISH RH	Not Necessary	73.00 F	*- FL
21	1		*FRONT DOOR LOCK RH	Not Necessary	239.00 F	*- FL
22	1		*FRONT DOOR FRAME, WINDOW REG RH	Not Necessary	87.00 F	*- FL
23	1		*REAR DOOR FRAME, WINDOW REG RH	Not Necessary	89.00 F	*- FL
24	1		*REAR DOOR LOCK RH	Not Necessary	188.00 F	*- FL
25	1		*REAR DOOR HANDLE BASE RH	Not Necessary	75.00 F	*- FL
26	1		*REAR DOOR HANDLE OUTER RH	Not Necessary	42.00 F	*- FL
27	1		*REAR DOOR LEVER OUTER HANDLE RH	Not Necessary	72.50 F	*- FL
28	1		*REAR DOOR CAP RH	Not Necessary	41.00 F	*- FL
29	1		*SIDE DOOR MIRROR COMPLETE RH	Broken	425.00 F	*425.00 FL
30	1		*REAR WINDOW MOULD	Necessary	85.00 F	*85.00 FL
31	1		*WHEEL CAP (2PCS)	Cut (1Pc Only)	112.00 F	*56.00 FL
32	1		*WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,095.50	4,586.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	909.20
Total Parts (\$\$)	8,095.50	3,676.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE NEW PARTS, REMOVE / REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR	New	1,200.00	1,000.00
2	CHECK WIRING AND PROPER FUNCTIONING	New	200.00	30.00
3	TO CONDUCT 4 WHEEL ALIGNMENT	New	100.00	60.00
4	SPRAY PAINT ON THE AFFECTED AREAS WITH 2K PAINT	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			2,700.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >