

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:

Our Ref : 0728/09/21

M/s : CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Attn : MOTOR CLAIMS DEPARTMENT

Page: 1

Date: 06/09/2021

Steve (LKK)

8/9/21, 3.00pm

WHL PR

After L/S

My Best Sky

10 days

Dear Sir/Madam,

.. ACCIDENT REPAIR ON : SLL7672J - 0
INSURED : BOLT CAR LEASING PTE LTD
DATE OF ACCIDENT : 30/08/2021
YOUR INSURED VEH NO: XD7827E

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

			S\$	S\$	S\$
REPLACEMENT OF PARTS					
1	FRONT FENDER RH	1 @	350.00	350.00	✓
2	FRONT SPLASH SHIELD RH	1 @	101.00	101.00	
3	FRONT PILLAR OUT RH	1 @	762.00	762.00	
4	PANEL SIDE SILL RH	1 @	924.00	924.00	
5	REAR PANEL FENDER RH	1 @	1,233.00	1,233.00	✓
6	FRONT DOOR RH	1 @	1,200.00	1,200.00	1962 ✓
7	FRONT DOOR WEATHERSTRIP RH	1 @	111.00	111.00	
8	FRONT DOOR HINGE UPPER RH	1 @	52.00	52.00	✓
9	FRONT DOOR HINGE LOWER RH	1 @	53.00	53.00	✓
10	REAR DOOR RH	1 @	1,048.00	1,048.00	✓
11	REAR DOOR WHEATHERSTRIP RH	1 @	111.00	111.00	
12	REAR DOOR HINGE 'A' RH	1 @	52.00	52.00	✓
13	REAR DOOR HINGE 'B' RH	1 @	54.00	54.00	✓
14	FRONT MOULD BELTLINE RH	1 @	86.00	86.00	
15	FRONT MOULD SASH RH	1 @	98.00	98.00	
16	FRONT DOOR GARNISH RH	1 @	52.00	52.00	
17	REAR MOULD BELTLINE RH	1 @	76.00	76.00	✓
18	REAR MOULD SASH RH	1 @	89.00	89.00	
19	REAR DOOR GARNISH RH	1 @	65.00	65.00	
20	REAR DOOR GARNISH RH	1 @	73.00	73.00	
21	FRONT DOOR LOCK RH	1 @	239.00	239.00	
22	FRONT DOOR FRAME, WINDOW REG RH	1 @	87.00	87.00	
23	REAR DOOR FRAME, WINDOW REG RH	1 @	89.00	89.00	
24	REAR DOOR LOCK RH	1 @	188.00	188.00	
25	REAR DOOR HANDLE BASE RH	1 @	75.00	75.00	
26	REAR DOOR HANDLE OUTER RH	1 @	42.00	42.00	
27	REAR DOOR LEVER OUTER HANDLE RH	1 @	72.50	72.50	
28	REAR DOOR CAP RH	1 @	41.00	41.00	
29	SIDE DOOR MIRROR COMPLETE RH	1 @	425.00	425.00	✓
30	REAR WINDOW MOULD	1 @	85.00	85.00	✓
31	WHEEL CAP (per RH)	1 @	56.00	112.00	56 ✓

4546

- 20%

3636.80

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0728/09/21

Page: 2
Date: 06/09/2021

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
				8,045.50
	SUB-TOTAL			
	*SPECIAL NETT			
32	WINDSCREEN SEALANT	1 @	50.00	50.00 40

LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE/REFIT ALL		1,200.00	1000
1	ATTACHMENT PARTS TO FACILITATE REPAIR			
1				
2	SPRAY PAINT ON THE AFFECTED AREAS		1,200.00	1000
2	WITH 2K PAINT.			
2				
3	CHECK WIRING AND PROPER FUNCTIONING.		200.00	30
3				
4	TO CONDUCT 4 WHEEL ALIGNMENT	2090	100.00	60
	Nett Total Before GST			10,795.50

Yours faithfully,


(Workshop Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 3636-80

A- 40

L- 2090

5766-80

L/S- 4613.44

= 4690