

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121009462/UUF3N2**Date:** 03/12/2021REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : FBL4241H **Insured Vehicle No :** SDS8999T

Date of Loss: 12/08/2021 Nature of Claim: TP Claim No: CDMPG21001492

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBL4241H**

Make & Model: YAMAHA MT-09, 847cc Engine No: N701E068447

Reg. Date: 14/10/2016 (Man. Year: 2016) Chassis No: JYARN29S000004672

Colour: Grey Odometer: 61419 km

Engine Capacity: 847 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70ZR17 Rear Tyre Size: 180/55ZR17

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,892.00	10,912.70	10,979.30	50.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	980.00	420.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,292.00	11,892.70	11,399.30	48.94
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	23,292.00	9,500.00	13,792.00	59.21
+ GST 7.00/7.00% (S\$)	1,630.44	665.00	965.44	59.21
Nett Amount (S\$)	24,922.44	10,165.00	14,757.44	59.21

INSPECTION

Date of Assignment: 08/09/2021

Date Inspected: 09/09/2021 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Dec 2021)	
Parts:	N/A	YAMAHA MT-09 847cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL4241H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	325.00 F	*185.00 FL
2	1		*HEADLAMP	Scratched	1,100.00 F	*1,100.00 FL
3	1		*FRONT WINDSHIELD	Scratched/Cracked	280.00 F	*210.00 FL
4	1		*FRONT SIGNAL LAMP O/S	Cut	160.00 F	*60.00 FL
5	1		*FRONT FORK ASSY N/S	Serviceable	1,990.00 F	*- FL
6	1		*FRONT FORK ASSY O/S	Bent/Twisted	1,990.00 F	*1,600.00 FL
7	1		*FRONT FORK UNDER BRACKET	Bent	685.00 F	*520.00 FL
8	1		*FRONT FORK UPPER STEM	Bent	690.00 F	*645.00 FL
9	1		*FRONT SPORT RIM	Bent/Warped	1,450.00 F	*980.00 FL
10	1		*FRONT BRAKE DISC O/S	Bent/Warped	515.00 F	*450.00 FL
11	1		*BRAKE LEVER	Scratched	140.00 F	*90.00 FL
12	1		*HANDLE BAR	Bent	520.00 F	*425.00 FL
13	1		*HANDLE BAR BALANCER O/S	Cut	60.00 F	*45.00 FL
14	1		*HANDLE BAR GRIP O/S	Not Necessary	85.00 F	*- FL
15	1		*MIRROR O/S	Cut	100.00 F	*85.00 FL
16	1		*FUEL TANK	Dented/Bent	1,680.00 F	*1,480.00 FL
17	1		*SET FUEL TANK PAD	Necessary/Cut	300.00 F	*280.00 FL
18	1		*FUEL TANK LOWER GARNISH O/S	Cut	420.00 F	*290.00 FL
19	1		*RADIATOR	Punctured	980.00 F	*980.00 FL
20	1		*RADIATOR CAP	Cut	38.00 F	*38.00 FL
21	1		*RADIATOR OUTER PROTECTOR	Cut/Twisted	420.00 F	*285.00 FL
22	1		*BODY FRAME	Repair	3,500.00 F	*- FL
23	1		*CLUTCH OUTER COVER O/S	Cut	490.00 F	*460.00 FL
24	1		*FRONT FOOT BRAKE PEDAL	Cut/Bent	165.00 F	*165.00 FL
25	1		*FRONT FOOT REST O/S	Cut	90.00 F	*90.00 FL
26	1		*FRONT FOOT REST BRACKET O/S	Serviceable	205.00 F	*- FL
27	1		*FRONT SIDE GARNISH O/S	Cut	260.00 F	*200.00 FL
28	1		*EXHAUST ASSY	Repair	1,200.00 F	*- FL
29	1		*REAR FOOT REST O/S	Not Necessary	180.00 F	*- FL
30	1		*REAR SLIDER O/S	Cut	120.00 F	*120.00 FL
31	1		*REAR SEAT CUSHION	Torn	450.00 F	*300.00 FL
32	1		*REAR SEAT COVER	Cut	600.00 F	*520.00 FL
33	1		*REAR BOX	Cut	500.00 F	*500.00 FL
34	1		*REAR BOX BRACKET	Serviceable	180.00 F	*- FL
35	1		*REAR LICENCE PLATE	Cut	12.00 FS	*10.00 FS
36	1		*FRONT LICENCE PLATE STICKER	Necessary	12.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,892.00	12,123.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	1,210.30
Total Parts (S\$)	21,892.00	10,912.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	0.00
2	TO STRAIGHTEN & REPAIR BODY FRAME	New	450.00	300.00
3	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	400.00	300.00
4	TO SPRAY PAINTING	New	500.00	380.00
Gross Labour Cost (\$\$)			1,400.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >