

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21009463/GVCE2**Date:** 21/09/2021**REFERENCE**

Insured/Claimant: LECUDDLES Policy No: DMCVSNW00106232001  
Date of Loss: 30/08/2021 Nature of Claim: OD Claim No: SNM21D204940/C01/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBF4469A**  
Make & Model: TOYOTA HIACE, 3.0 D X (M) Engine No: 1KD2636119  
Reg. Date: 28/10/2016 (Man. Year: 2016) Chassis No: KDH2015023692  
Colour: White Odometer: 0 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$50,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15  
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm  
Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>- Excess (S\$)</b>	350.00	350.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>-350.00</b>	<b>-350.00</b>	<b>0.00</b>	<b>0.00</b>

**INSPECTION**

Date of Assignment: 08/09/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)  
Date Inspected: 08/09/2021 Inspected At: Car City Auto Centre Pte Ltd (HQ)  
Estimated Period of Repair: 0.0 days Blk 9006 #01-198, Tampines Street 93  
Singapore 528840

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$50,000.00
OMV :	\$31,523.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$20,483.00
COE Rebate (2) :	\$10,516.00
Total Rebate (1) + (2) = :	\$10,516.00

The total amount incurred will be Market Value \$50,000.00 minus Total Rebate \$10,516.00 = \$39,484.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 21 Sep 2021)

**Parts:**            213                    TOYOTA HIACE 3.0 D X (M) (Catalogue:Merimen Singapore 1.0)

**Labour:**        Repairer's            (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBF4469A)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**