

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/AIG21009468/VQF3E2**Date:** 21/09/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100475468
<b>Claimant Vehicle No :</b>	SKB3806G	<b>Insured Vehicle No :</b>	SLE4404Z
Date of Loss:	03/09/2021	Nature of Claim:	TP
		Claim No:	1620648227SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKB3806G</b>		
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Engine No:	R18A1788975
Reg. Date:	19/03/2009 (Man. Year: 2008)	Chassis No:	RN61080102
Colour:	Red	Odometer:	327374 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R16	Rear Tyre Size:	225/40Z R16
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

INSPECTION

Date of Assignment:	08/09/2021	
Date Inspected:	09/09/2021	Inspected At: Garage 13 Pte Ltd (HQ) 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46 Singapore 415875
Estimated Period of Repair:	5.0 days	

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$49,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR BUMPER (FIBER)	Cracked	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER BRACKET RH	Cracked	0.00 F	*- F
6	1		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Dented	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
10	1		*TAILGATE	Buckled	0.00 F	*- F
11	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
12	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
13	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
14	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
15	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >