

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21009471/T1TCE2

Date: 18/01/2022

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00156502000

Claimant Vehicle No : SBS8342L

Insured Vehicle No : SMV8670T

Date of Loss: 30/08/2021

Nature of Claim: TP

Claim No: SNM21D205055/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS8342L**

Make & Model: SCANIA KEB4X2, 11.7 D (M)

Engine No: 6385375

Reg. Date: 22/09/2008 (Man. Year: 2008)

Chassis No: YS2K4X20001861583

Colour: Multi-colour

Odometer: 1116259 km

Engine Capacity: 8867 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8/8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	939.00	939.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	800.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,739.00	1,739.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	121.73	121.73	0.00	0.00
Nett Amount (S\$)	1,860.73	1,860.73	0.00	0.00

INSPECTION

Date of Assignment: 10/01/2022

Date Inspected: 09/09/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Sbs Transit Ltd (Bedok) (HQ)
1470 BEDOK NORTH AVE 4
Singapore 489946

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Jan 2022)	
Parts:	N/A	SCANIA KEB4X2 11.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS8342L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE PANEL.O/S&N/S.ALUM	Bent	79.00 F	*79.00 F
2	1		*RADIATOR GRILL JL~KL;SIDE PANEL ASSY	Bent	612.00 F	*612.00 F
3	1		*BUMPER.REAR.F/G	Cracked	248.00 F	*248.00 F
					Total Parts (S\$)	939.00
						939.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CONTRACTOR LABOUR COST	New	800.00	800.00
2	WORKSHOP LABOUR COST (NPA)	New	0.00	0.00
			Gross Labour Cost (\$)	800.00
				800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >