

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009473/EUCN2**Date:** 02/12/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00150792001

Claimant Vehicle No : SFY9655Z **Insured Vehicle No :** SJP9088K

Date of Loss: 06/09/2021 Nature of Claim: TP Claim No: SNM21D205059/C2/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFY9655Z**

Make & Model: MAZDA 6, 2.0 R Hatch (GH) (A) Engine No: PY20873071

Reg. Date: 02/06/2017 (Man. Year: 2016) Chassis No: JM6GL103100109929

Colour: Red Odometer: 51576 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R19 Rear Tyre Size: 225/45R19

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,258.60	5,875.90	2,382.70	28.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,930.00	7,760.00	3,170.00	29.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	19,188.60	13,635.90	5,552.70	28.94
+ GST 7.00/7.00% (\$\$)	1,343.20	954.51	388.69	28.94
Nett Amount (\$\$)	20,531.80	14,590.41	5,941.39	28.94

INSPECTION

Date of Assignment: 08/09/2021

Date Inspected: 09/09/2021 Inspected At: 27A Tanjong Penjuru
Repairer: Trans Eurokars Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2021)
Parts:	144	MAZDA 6 2.0 R Hatch (GH) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFY9655Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROCKER PANEL RH	Dented	1,071.00 FS	*1,071.00 FS
2	2		*COVER,HOLE	Necessary	22.80 FS	*22.80 FS
3	1		*GUARD STONE RH	Necessary	17.40 FS	*17.40 FS
4	1		*REAR DOOR RH	Dented	1,111.60 FS	*1,111.60 FS
5	1		*STRIPE NO 4 (R) BODY SIDE	Necessary	23.10 FS	*23.10 FS
6	1		*STRIPE NO 2 (R) BODY SIDE	Necessary	15.50 FS	*15.50 FS
7	1		*MOULD BELTLINE REAR DOOR RH	Not Necessary	72.20 FS	*- FS
8	1		*WEATHERSTRIP REAR DOOR RH	Not Necessary	143.70 FS	*- FS
9	1		*FASTENER (R), WEATHERS	Necessary	12.30 FS	*12.30 FS
10	10		*FASTENER	Necessary	34.00 FS	*34.00 FS
11	1		*CHECKER,DOOR RR RH	Not Necessary	65.70 FS	*- FS
12	1		*GROMMET	Necessary	2.40 FS	*2.40 FS
13	1		*CLIP	Necessary	2.40 FS	*2.40 FS
14	1		*FASTENER	Necessary	3.20 FS	*3.20 FS
15	10		*GROMMET SCREW	Necessary	30.00 FS	*30.00 FS
16	1		*GROMMET SCREW	Necessary	3.80 FS	*3.80 FS
17	9		*FASTENER	Necessary	64.80 FS	*64.80 FS
18	1		*GARNISH REAR DOOR RH	Necessary	95.00 FS	*95.00 FS
19	1		*GARNISH (R) REAR DOOR	Necessary	102.90 FS	*102.90 FS
20	6		*CLIP,GARNISH	Necessary	73.80 FS	*73.80 FS
21	1		*BRACKET SIDE STEP RH	Cut	177.60 FS	*177.60 FS
22	10		*CLIP	Necessary	100.00 FS	*100.00 FS
23	2		*CLIP	Necessary	13.00 FS	*13.00 FS
24	1		*REAR BUMPER	Crushed	1,230.30 FS	*1,230.30 FS
25	2		*TAPE,PROTECTOR	Necessary	17.20 FS	*17.20 FS
26	1		*SPLASH SHIELD RH REAR	Crushed	53.90 FS	*53.90 FS
27	6		*FASTENER	Necessary	18.00 FS	*18.00 FS
28	1		*GASKET TAIL LAMP RH	Necessary	27.70 FS	*27.70 FS
29	1		*GASKET TAIL LAMP LH	Necessary	27.70 FS	*27.70 FS
30	1		*REAR DAMPER RH	Not Necessary	322.00 FS	*- FS
31	1		*ARM UPPER REAR RH	Not Necessary	241.10 FS	*- FS
32	1		*TARAILING ARM REAR RH	Not Necessary	258.50 FS	*- FS
33	1		*LATERAL ARM REAR RH	Not Necessary	138.00 FS	*- FS
34	1		*KNUCKLE REAR RH	Not Necessary	631.10 FS	*- FS
35	1		*HUB WHEEL BEARING REAR RH	Not Necessary	480.40 FS	*- FS
36	1		*WHEEL,DISC 19X7.5	Cut	1,497.80 FS	*1,497.80 FS
37	1		*VALVE,AIR TYRE	Necessary	6.70 FS	*6.70 FS
38	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,258.60	5,875.90
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR DOOR RH AND ROCKER PANEL RH	New	3,960.00	2,640.00
2	TO RESPRAY REAR BUMPER,REAR DOOR RH AND ROCKER PANEL RH	New	2,520.00	1,890.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	New	180.00	180.00
4	TO TRANSFER THE DOOR MECHANISM	New	330.00	330.00
5	TO REPLACE AXLE AND SUSPENSION MECHANISM	New	630.00	0.00
6	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
7	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	80.00
8	TO TRANSFER REVERSE SENSORS	New	660.00	330.00
9	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	150.00
10	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
11	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOUC)	New	160.00	160.00
12	SPRAY RHR FENDER,RHF DOOR	New	1,260.00	1,260.00
Gross Labour Cost (S\$)			10,930.00	7,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >