

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009475/GQCIN2**Date:** 15/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00037162102

Claimant Vehicle No : SMY3166A **Insured Vehicle No :** YL6709R

Date of Loss: 30/08/2021 Nature of Claim: TP Claim No: SNM21D204995/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY3166A**

Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2648086A

Reg. Date: 30/10/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1478526

Colour: Purple Odometer: 143199 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60R17 Rear Tyre Size: 225/60R17

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,347.20	3,633.34	2,713.86	42.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,280.00	1,180.00	47.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,807.20	4,913.34	3,893.86	44.21
Approved Total (Overridden) (\$\$)		3,900.00		
(\$\$)	8,807.20	3,900.00	4,907.20	55.72
+ GST 7.00/7.00% (\$\$)	616.50	273.00	343.50	55.72
Nett Amount (\$\$)	9,423.70	4,173.00	5,250.70	55.72

INSPECTION

Date of Assignment: 10/09/2021

Date Inspected: 09/09/2021 Inspected At: Ricardo Auto Centre Pte Ltd (HQ)
160 Sin Ming Drive, #02-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Apr 2022)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMY3166A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	3,062.00 F	*2,938.00 FN
2	1		*TAILGATE LOGO	Necessary	64.90 F	*64.90 FN
3	1		*TAILGATE PLATE-QASHQAI	Necessary	94.90 F	*78.00 FN
4	1		*TAILGATE LOCK	Necessary	173.70 F	*116.70 FN
5	1		*BACK WEATHERSTRIP	Not Necessary	167.10 F	*- FN
6	1		*REAR BUMPER	Deformed	796.80 F	*717.00 FN
7	10		*REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FN
8	1		*REAR BUMPER SIDE RETAINER LH & RH	O/s Deformed/N/s Not Necessary	90.00 F	*38.00 FN
9	1		*REAR BUMPER SPONGE	Not Necessary	141.40 F	*- FN
10	2		*REAR BUMPER SIDE BRACKET LH & RH	Not Necessary	283.80 F	*- FN
11	2		*REAR BUMPER SIDE BRACKET	Not Necessary	80.00 F	*- FN
12	1		*REAR END PANEL	Not Necessary	482.60 F	*- FN
13	1		*REAR END PANEL PLATE	Not Necessary	130.00 F	*- FN
14	1		*REAR BUMPER LOWER LID	Not Necessary	380.00 F	*- FN
15	1		*REAR BUMPER SENSOR (4 PCS)	Not Necessary	320.00 F	*- FN
16	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	6,347.20	4,032.60
- Nett Item Discount on N Items 0.00/10.00% (S\$)	0.00	399.26
Total Parts (S\$)	6,347.20	3,633.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT,WELD & STRAIGHTEN REAR PORTION OF CAR CAUSED BY ACCIDENT.ADJUST & REPLACE DAMAGE PARTS	New	1,000.00	450.00
2	TO REMOVE REAR WINDSCREEN GLASS ENABLE TO REPLACE TAILGATE AND FIX SAME	New	120.00	120.00
3	TO TUFF COAT REPAIRED AREAS	New	80.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	60.00	60.00
5	TO SPRAY PAINT ON REPAIRED AREA	New	1,200.00	650.00
Gross Labour Cost (\$)			2,460.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >