



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2108773

INV Date 20/12/2021

Reference CC4/LPC21009478/Ara3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBG 8089G
Insured Veh. 5025S
Claim No. 20/21/21/VC40/024928
Policy No. Z/20/VC40/109099-001
Accident Date 06/09/2021
Inspection Date 08/09/2021

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21009478/Ara3q2 Date: 20/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	5025S	Veh. Inspected	GBG 8089G	
Policy No.	Z/20/VC40/109099-001	Coverage (\$)	0.00	
Claim No.	20/21/21/VC40/024928	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	08/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAXUS G10	c.c	1850	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LSKG4GL10HA061686	Colour	SILVER	
Odometer	93017 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/70 R16C	FALKEN	6 mm	
L/H Front Tyre	215/70 R16C	FALKEN	6 mm	
R/H Rear Tyre	215/70 R16C	FALKEN	6 mm	
L/H Rear Tyre	215/70 R16C	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2021	Inspection Date	08/09/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 8089G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER N/S RETAINER	NOT NECESSARY	110.30	-
1	N/S SLIDING DOOR	DENTED	2,698.20	1,850.00
1	N/S SLIDING DOOR LOCK	NOT NECESSARY	436.20	-
1	N/S SLIDING DOOR SLIDING ARM UPPER	NOT NECESSARY	232.40	-
1	N/S SLIDING DOOR SLIDING ARM LOWER	NOT NECESSARY	286.50	-
1	N/S SLIDING DOOR SLIDING ARM MIDDLE	NOT NECESSARY	255.40	-
1	REAR BUMPER N/S RETAINER	NOT NECESSARY	112.40	-
1	REAR BUMPER N/S REFLECTOR	NOT NECESSARY	140.60	-
	LESS 10% DISCOUNT		-427.20	-185.00
			3,844.80	1,665.00
1	N/S SLIDING DOOR BLACK STICKER (SN)	NECESSARY	145.00	60.00
	LESS 10% DISCOUNT		-14.50	-
			130.50	60.00
	<u>SPECIAL NETT ITEMS</u>			
10	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
1	FRONT O/S DOOR COMPANY STICKER (SN)	NECESSARY	30.00	30.00
10	REAR BUMPER CLIPS (SN)	NOT NECESSARY	80.00	-
			190.00	30.00
	<u>LABOUR</u>			
	TO DISMANTLE ,REMOVE AND REFIT FRONT AND REAR BUMPER .		1,000.00	400.00
	TO SPRAY PAINTING BODY PARTS & RIM .		1,600.00	1,000.00
	TO REMOVE AND REPLACE N/S SLIDING DOOR FITTINGS .		200.00	60.00
	TO CHECK WIRING .		120.00	30.00
	TO RE-SEAL ANTI-RUST.		300.00	60.00
			3,220.00	1,550.00
	GRAND TOTAL		7,385.30	3,305.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00
---	--	--	----------

Report Ref No. CC4/LPC21009478/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 8089G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

