

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21009479/VQF3E2**Date:** 21/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210065503
Claimant Vehicle No :	FBF497U	Insured Vehicle No :	SNA5560X
Date of Loss:	23/08/2021	Nature of Claim:	TP
		Claim No:	4536131540SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBF497U	Engine No:	5YP303041
Make & Model:	YAMAHA T135, 135cc	Chassis No:	5YP303041
Reg. Date:	11/01/2011 (Man. Year: 2010)	Odometer:	56212 km
Colour:	Blue		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	70/90-17
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	09/09/2021	He Xin Motor (HQ)
Date Inspected:	09/09/2021 Inspected At:	BLK 25 KAKI BUKIT ROAD 4 #01-75
		SYNERGY@KB SINGAPORE 417800
		Singapore 417800
Estimated Period of Repair:	4.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$6,000 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT TYRE RIM SPOKE	Scratched	0.00 F	*- F
2	1		*FRONT FORK ASSY	Bent	0.00 F	*- F
3	1		*FRONT HEADLAMP	Cracked	0.00 F	*- F
4	1		*FRONT LH SIGNAL LAMP	Cracked	0.00 F	*- F
5	1		*FRONT RH SIGNAL LAMP	Cracked	0.00 F	*- F
6	1		*HANDLE BAR	Bent	0.00 F	*- F
7	1		*HANDLE BAR BALANCER RH	Bent	0.00 F	*- F
8	1		*CLUTCH LEVER	Scratched	0.00 F	*- F
9	1		*SIDE FAIRING	Scratched	0.00 F	*- F
10	1		*SIDE FAIRING TOP GARNISH	Scratched	0.00 F	*- F
11	1		*SIDE STAND	Bent	0.00 F	*- F
12	1		*MAIN STAND	Bent	0.00 F	*- F
13	1		*KICK STARTER RUBBER	Bent	0.00 F	*- F
14	1		*KICK STARTER LEVER	Bent	0.00 F	*- F
15	1		*REAR BOX BRACKET	Bent	0.00 F	*- F
16	1		*HANDLE BAR BALANCER LH	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >