

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21009480/UQCN2**Date:** 11/10/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00145662100

**Claimant Vehicle No :** SLC2927E **Insured Vehicle No :** SMM1283X

Date of Loss: 05/09/2021 Nature of Claim: TP Claim No: SNM21D205061/C02/LEEPG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLC2927E**

Make & Model: HONDA JAZZ, 1.3 (A) Engine No: L13B11010285

Reg. Date: 09/05/2016 (Man. Year: 2016) Chassis No: JHMGK3850GX236450

Colour: Red Odometer: 125150 km

Engine Capacity: 1318 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,978.84	1,492.72	486.12	24.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,810.00	1,700.00	1,110.00	39.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,788.84</b>	<b>3,192.72</b>	<b>1,596.12</b>	<b>33.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		
<b>(S\$)</b>	4,788.84	2,550.00	2,238.84	46.75
<b>+ GST 7.00/7.00% (S\$)</b>	335.22	178.50	156.72	46.75
<b>Nett Amount (S\$)</b>	<b>5,124.06</b>	<b>2,728.50</b>	<b>2,395.56</b>	<b>46.75</b>

**INSPECTION**

Date of Assignment: 09/09/2021

Date Inspected: 27/09/2021 Inspected At: Progressive Car Care Pte Ltd (HQ)  
Blk 3022A Ubi Road 1, #01-45/46  
Singapore 408716

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Oct 2021)
<b>Parts:</b>	144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC2927E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	851.80 FL	*779.20 FL
2	1		*SET REAR BOOT GLASS MOULDING	Necessary	118.60 FL	*118.60 FL
3	1		*REAR BOOT RUBBER	Twisted	92.30 FL	*92.30 FL
4	1		*REAR BOOT TOP LOCK	Shorted	183.50 FL	*183.50 FL
5	1		*REAR BOOT BOTTOM LOCK	Not Necessary	25.70 FL	*- FL
6	1		*REAR BOOT JAZZ WORDING	Necessary	20.90 FL	*20.90 FL
7	1		*REAR BUMPER	Dented	529.00 FL	*529.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
9	1		*REAR BUMPER SIDE HOLDER-LH	Necessary	14.70 FL	*14.70 FL
10	1		*REAR BUMPER SIDE HOLDER-RH	Necessary	14.70 FL	*14.70 FL
11	1		*REAR BUMPER LOWER GARNISH BLACK	Not fitted	14.60 FL	*- FL
12	1		*REAR PANEL	Repair	390.20 FL	*- FL
13	1		*REAR PANEL TOP GARNISH	Not Necessary	60.80 FL	*- FL
14	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	35.00 FS	*- FS
15	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,449.80</b>	<b>1,850.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	470.96	358.18
<b>Total Parts (S\$)</b>	<b>1,978.84</b>	<b>1,492.72</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK OUT DENTS,CUT/WELD,REAR PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	1,000.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)	New	1,200.00	800.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO TUFF-KOTE	New	120.00	30.00
5	TO REMOVE,REFIX REAR WINDSCREEN	New	120.00	120.00
6	TO REMOVE,REFIX REAR GARNISH,CARPET,CUSHION & RELATED PARTS	New	150.00	80.00
7	TO RESET CHECK LIGHT	New	70.00	0.00
8	TO TRANSFER REAR BUMPER SENSOR	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,810.00</b>	<b>1,700.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >