



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 8589X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BOOTLID	TO REPAIR SEE LABOUR	702.00	-
4	REAR BOOTLID EMBLEM	NECESSARY	184.00	184.00
1	REAR BOOTLID LOCK	DAMAGED	246.00	246.00
1	REAR BOOTLID RUBBER	CUT	104.00	104.00
1	REAR BUMPER	DEFORMED	756.00	756.00
8	REAR BUMPER CLIPS	NECESSARY	32.00	32.00
2	REAR BUMPER SIDE RETAINER	NECESSARY	92.00	92.00
5	REAR BUMPER REINFORCEMENT	DAMAGED	75.00	75.00
1	REAR BUMPER LOWER GARNISH	DEFORMED	296.00	296.00
2	REAR BUMPER REFLECTOR	O/S CUT	76.00	38.00
2	REAR BUMPER REVERSE SENSOR	DAMAGED	310.00	310.00
1	REAR BUMPER REINFORCEMENT BEAM	CRACKED	412.00	344.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	512.00	-
1	REAR END PANEL GARNISH	DEFORMED	129.00	129.00
1	REAR SPAREWHEEL TOP COVER GARNISH	TORN	371.00	179.00
1	REAR EXHAUST PIPE CHROME COVER	CUT	180.00	180.00
	LESS 10% DISCOUNT		-	-296.50
			4,477.00	2,668.50
<b><u>LABOUR</u></b>				
	WIRING.		50.00	30.00
	TO SPRAY PAINTING.		650.00	600.00
	TO REMOVE AND REFIX REAR EXHAUST PIPE & CHROME COVER.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR INTERIOR UPHOLSTERY.		80.00	50.00
	TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED PANEL FOR RUST PROTECTION.		80.00	50.00
	TO MEASURE, DRILL THE REPLACED REAR BUMPER, POSITION & REINSTALL REVERSE SENSOR, CONTROL UNIT, CAMERA ASSY & TEST FOR FUNCTIONING.		80.00	50.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGE FOR PANEL BEATING KIA & WELDING, REMOVING ALL DAMAGE PARTS AND REPLACING OF THE NEW PARTS ETC. INCLUSIVE OF THE REPAIR OF REAR BOOTLID AND REAR END PANEL.		650.00	600.00
			1,670.00	1,380.00
GRAND TOTAL			6,147.00	4,048.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,200.00

Report Ref No. CS/TP21009481/Avce2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.