

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21009482/AVCN2**Date:** 01/10/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00178852000

**Claimant Vehicle
No :** SJH7050Z**Insured
Vehicle No :** SLR7735E

Date of Loss: 06/09/2021

Nature of Claim: TP

Claim
No: SNM21D205062/C02/LEWLC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SJH7050Z**

Make & Model: TOYOTA ALLION, 1.5 (A)

Engine No: 1NZA120201

Reg. Date: 20/08/2008 (Man. Year: 2008)

Chassis No: NZT2603029504

Colour: Red

Odometer: 181331 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55R15

Rear Tyre Size: 195/55R15

Front Left Side: Double Star 6 mm

Rear Left Side: Double Star 6 mm

Front Right Side: Double Star 6 mm

Rear Right Side: Double Star 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,003.40	3,122.87	3,880.53	55.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,900.00	1,750.00	47.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,653.40	5,022.87	5,630.53	52.85
Approved Total (Overridden) (\$\$)		4,000.00		
Nett Amount (\$\$)	10,653.40	4,000.00	6,653.40	62.45

INSPECTION

Date of Assignment: 09/09/2021

Date Inspected: 09/09/2021

Inspected At: Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Oct 2021)
Parts:	143	TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJH7050Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,490.50 FL	*968.40 FL
2	1		*REAR BUMPER SIDE RETAINER	N/s Damaged	130.00 FL	*65.00 FL
3	1		*REAR BUMPER BRACKET	N/s Dented	156.00 FL	*78.00 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	256.00 FL	*- FL
5	2		*REAR BUMPER CORNER BRACKET	Not Necessary	50.00 FL	*- FL
6	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
7	1		*REAR BOOTLID PANEL	Dented	1,086.20 FL	*951.60 FL
8	1		*REAR BOOTLID INNER LOCK	Damaged	395.40 FL	*225.00 FL
9	1		*REAR BOOTLID LOGO	Necessary	75.40 FL	*75.40 FL
10	1		*REAR BOOTLID EMBLEM (ALLION)	Necessary	72.80 FL	*72.80 FL
11	1		*REAR BOOTLID WEATHER STRIP	Not Necessary	286.70 FL	*- FL
12	1		*REAR BOOTLID DETECTOR SENSOR	Not Necessary	494.10 FL	*- FL
13	1		*REAR TAILLAMPS	N/s Cracked	1,172.80 FL	*378.20 FL
14	1		*REAR END PANEL	Dented	598.70 FL	*598.70 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed	257.40 FL	*257.40 FL
16	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FL	*10.00 FL
17	1		*REAR SPARE TYRE TOP GARNISH	Not Necessary	298.40 FL	*- FL
18	1		*REAR SPARE TYRE PANEL	Not Necessary	1,270.80 FL	*- FL
19	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
20	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*REAR SPARE TYRE PANEL INSULATOR	Not Necessary	250.00 FS	*- FS
22	1		*REVERSE SENSOR SET (4-EYES)	Damaged	380.00 FS	*280.00 FS
23	1		*REAR NUMBER PLATE W/BASE GARNISH	Not Necessary	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,056.20	4,050.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,052.80	927.63
Total Parts (\$\$)	7,003.40	3,122.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH	New	150.00	80.00
5	TO REMOVE & INSTALL SPARE TYRE COMPARTMENT TRIM & GARNISH	New	150.00	60.00
6	TO DRILL,RE-POSITION REVERSE SENSOR & ALIGN	New	150.00	50.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	0.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	80.00
Gross Labour Cost (\$\$)			3,650.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >